Santa Fe, New Mexico MISCELLANEOUS NOTICES Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the Section is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission. Indicate nature of notice by checking below:	
NOTICE OF INTENTION TO TEST CASING SHUT-OFF NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NOTICE OF INTENTION TO REPAIR WELL NOTICE OF INTENTION TO PLUG WELL	
NOTICE OF INTENTION TO DEEPEN WELL	
Midland, Texas October 8, 1945 Place Date	
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico. Gentlemen: Following is a notice of intention to do certain work as described below at the	riki /a
Plymouth 011 Company Santa Fe Well No. 1-A in SW/4 of Company or Operator Lease	Ne /#
of Sec. 13 , T. 15 N , R. 10N , N. M. P. M., Wildest Field,	
County. FULL DETAILS OF PROPOSED PLAN OF WORK	
FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION	
FORMOW INDIRECTIONS IN THE WORLD IN THE PROPERTY OF THE CONTRACTOR	
Fill hole from 6210', total depth, to 2040' with heavy mud - Spot 15 sack cement plug at 1040' - Fill hole to 10' of surface with heavy mud - 10' cement plug in top of 13-3/8" - With proper Marker on top of surface - Leave all of 13-3/8" surface casing in hole, cemented from bottom to top.	
Fill hole from 6210', total depth, to 2640' with heavy mud - Spot 15 sack cement plug at 1040' - Fill hole to 10' of surface with heavy mud - 10' cement plug in top of 13-3/8" - With proper Marker on top of surface - Leave all of 13-3/8" surface casing in hole, cemented from bottom to top. Approved	
Fill hole from 6210', total depth, to 1040' with heavy mud - Spot 15 sack cement plug at 1040' - Fill hole to 10' of surface with heavy mud - 10' cement plug in top of 13-3/8" - With proper Marker on top of surface - Leave all of 13-3/8" surface casing in hole, cemented from bottom to top. Approved	

A PROPERTY OF A STATE OF A STATE

MAM.

garantina di Kalendaria di Mangazia di Kalendaria di K

ANTO, A. CO. Aptraytonamy A DELTA DE ZEZ ALIA