

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAIL TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL OR TO DEEPEN OR TO PLUG BAIL TO A DIFFERENT RESERVOIR" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Unknown
2. Name of Operator James Patcher <i>for Mary M Greer</i>	8. Farm or Lease Name Marjory M. Greer
3. Address of Operator Bloomfield Oilfield Service Co. Box 1641 Bloomfield, N.M.	9. Well No. Red Mountain # 7
4. Location of well UNIT LETTER B, 100 FEET FROM THE N LINE AND 2475 FEET FROM THE E LINE, SECTION 29 TOWNSHIP 20N RANGE 9W NMPM.	10. Field and Pool, or Wildcat Menefee
11. Elevation (Show whether DF, RT, GR, etc.)	12. County McKinnley

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-25-81 - Road rig and equipment to Red Mountain lease

9-26-81 - Moved rig and equipment on location and rigged up

9-28-81 - Weld on well head and install flow nipple and stripper head pickup 3 7/8 bit and tubing, cleaned out to 443, mixed and pumped 15 sacks class A cement, plug set from 443 to 315, pulled tubing back to 150 ft. Mixed and pumped 15 sacks class A cement. Plug set from 150 ft. to 30 ft., pulled to 30 ft., mixed and pumped 10 sacks class A cement. Rig down and move rig and equipment off location.

10-9-81- Clean location, level pits, install dry hole marker

10-9-81 - Location ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jeff A. Edmister TITLE Deputy Oil & Gas Inspector DATE 10-12-81

APPROVED BY Jeff A. Edmister TITLE Deputy Oil & Gas Inspector DATE 10-15-81