

(SUBMIT IN TRIPLICATE)

Indian Agency **Window Rock**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee **Navajo**
Lease No. **1-149-Ind.-61823**

EX-12-61

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 20th, 19 **59**

Well No. **1** is located **720** ft. from **N** line and **620** ft. from **E** line of sec. **12**
SW 1/4 Sec. 12 **27N** **13W** **N.M.P.M.**
(Section) (Twp.) (Range) (Meridian)
Window Rock **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5852** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mud logging points, and all other important proposed work)

Drilled to TD 1985'. Unable to locate old hole. Spotted cement plugs as follows:

**30 sacks from 1985' to 1895'.
30 sacks from 1900' to 1200'.
40 sacks from 200' to 50'.**

10-sack plug spotted in top of 8-5/8" casing, which was left in the hole. Erected dry hole marker. Well plugged and abandoned.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **HANSON-HOFFMAN-CHENIER DRILLING CORP.**
Address **158 Petroleum Center Building**
Farmington, New Mexico

By **Walter Green**
Vice-President

ILLEGIBLE



