

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
Unknown	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" - (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - P & A'd		7. Unit Agreement Name
2. Name of Operator Southland Royalty Company		8. Farm or Lease Name Hartman
3. Address of Operator P. O. Drawer 570, Farmington, New Mexico 87401		9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> , <u>2310</u> FEET FROM THE <u>north</u> LINE AND <u>900</u> FEET FROM THE <u>west</u> LINE, SECTION <u>28</u> TOWNSHIP <u>29N</u> RANGE <u>11W</u> N.M.P.M.		10. Field and Pool, or Wildcat Fulcher Kutz P.C.
15. Elevation (Show whether DF, RT, GR, etc.) 5413' GR		12. County San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:


SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Re-plug an abandoned well</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

### PROPOSE TO RE-PLUG THIS WELL IN THE FOLLOWING MANNER:

- MIRU
- Drill out surface plug from 0' to 120'.
- Test casing and bottom plug with packer.
- After we have determined the extent of damage to the casing a suitable cement program will be discussed with New Mexico Field Inspectors and an exact procedure can be agreed upon.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles G. Goulson TITLE Petroleum Engineer DATE Feb. 9, 1981

APPROVED BY Original Signed by CHARLES GOULSON TITLE DEPUTY OIL & GAS INSPECTOR DIST. # DATE FEB 10 1981

CONDITIONS OF APPROVAL, IF ANY: