

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole</u>		7. Unit Agreement Name
2. Name of Operator <u>Bloomfield Oil and Gas by Trend, Inc.</u>		8. Farm or Lease Name <u>Bergin</u>
3. Address of Operator <u>P.O. Box 915, Flora Vista, New Mexico 87415</u>		9. Well No. <u>#9</u>
4. Location of Well UNIT LETTER <u>G</u> <u>2430</u> FEET FROM THE <u>N</u> LINE AND <u>1920</u> FEET FROM THE <u>E</u> LINE, SECTION <u>21</u> TOWNSHIP <u>29</u> RANGE <u>11 W</u> N.M.P.M.		10. Field and Pool, or Wildcat <u>St. James</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>5450</u>		12. County <u>San Juan</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
- 10/31/'84 Dug out , built cellar & installed it. Pumped out water. Put on 10" nipple
11/1/'84 and flange.
- 11/11/'84 Moved rig & equipment to location. Started to rig up.
- 11/12/'84 Rigged up, run tbg., hit bridge at 15'. Drilled on junk iron 3 hrs., made 5' S.D.O.N
- 11/13/'84 Drilled on junk at 20'. Made 8" in 7 hrs. Wore out 2 conventional bits & 1 tungsten carbide bit. Shut down to construct impression block.
- 11/14/'84 Run impression block, got picture of rectangular junk laying vertical in hole. Run spear & bumper sub, didnt get fish. Run another spear unsuccessful. Run 2 3/8" tbg. Tried to get past fish with notched collar but it would not go. Run 3/4" tbg., got past top of junk 5'. Worked & rotated tbg. 1 hr. deeper, Pulled tbg. and 4' was cut off by junk.
- 11/15/'84 Run 2 3/8" tbg. to 21'. Mixed 20 sx. cement & squeezed 10 sx. in formation & 10 sx. from 21' to surface. Mixed 30 sx. cement & filled cellar. Cemented dry hole marker in surface pipe. Cleaned & leveled location.

RECEIVED

DEC 04 1984

OIL CON. DIV

DIST. 3

DATE 11/21/'84

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles Olson

TITLE Manger

Original Signed by CHARLES OLSON

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE DEC 04 1984

CONDITIONS OF APPROVAL, IF ANY: