

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Kendall & Associates, Inc.		8. Farm or Lease Name Hare
3. Address of Operator 719 West Apache Farmington, New Mexico 87401		9. Well No. 2
4. Location of Well UNIT LETTER <u>G</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>23</u> TOWNSHIP <u>29N</u> RANGE <u>11W</u> NMPM.		10. Field and Pool, or Wildcat Bloomfield Farmington
15. Elevation (Show whether DF, RT, GR, etc.) 5483 Gr		12. County San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 10-11-83 Pull rods and 2" tubing. Tag bottom at TD 738'.
- 10-12-83 Spot acid and soak @500 psia. **OPEN HOLE 710-738**,
Pump 12 bbl 15% HCL plus 5 bbl water at 1.5 B/M,
max pressure 700 psia.
Swab back all acid in 3 hrs.
- 10-13-83 Swab down - Show oil, slight show gas.
Ran pump and tbg. Set 2" @700'.
- 10-14-83 To install pump jack & tank battery.

RECEIVED
OCT 18 1983
OIL CON. DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Frank T. Chavez* TITLE Agent DATE 10-17-1983

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: