

COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Form or Lease Name	
H. D. Abrams	
9. Well No.	
5	
10. Field and Pool, or Wildcat	
12. County	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)


1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Bloomfield Oil & Gas Company Bedford, Inc. agent for & State of New Mexico
3. Address of Operator P. O. Box E, Farmington, New Mexico 87401
4. Location of Well UNIT LETTER E 1620 FEET FROM THE N LINE AND 300 FEET FROM THE W LINE, SECTION 23 TOWNSHIP 29N RANGE 11W NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The Oil Conservation Division has employed Bedford, Inc. to plug & abandon this well as follows:

1. Set plug from 670' to 55'
2. Perf. @ 150' to plug from 150' to 50' inside & outside of 6 5/8" casing
3. Set P & A marker & clean loc.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Larry A. Bedford</u>	TITLE <u>Agent for State</u>	DATE <u>9-26-78</u>
APPROVED BY <u>AR Kendrick</u>	TITLE <u>SUPERVISOR</u>	DATE <u>NOV 29 1978</u>
CONDITIONS OF APPROVAL, IF ANY:		