

COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Hare	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
12. County	
San Juan	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)


1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Finley & Johanson Bedford, Inc. agent for State of New Mexico
3. Address of Operator P. O. Box E, Farmington, New Mexico 87401
4. Location of Well UNIT LETTER C 175 FEET FROM THE N LINE AND 1570 FEET FROM THE W LINE, SECTION 22 TOWNSHIP 29N RANGE 11W NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

The Oil Conservation Division has employed Bedford, Inc. to plug and abandon this well as follows:

1. Set plug from 700' to 525'
2. Perf. @ 200' set plug inside & outside 6" casing from 200' to 100'
3. Set P & A marker, clean & level loc.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Larry A. Bedford</u>	TITLE <u>Agent for Operator</u>	DATE <u>9-26-78</u>
APPROVED BY <u>AL Hendrick</u>	TITLE <u>SUPERVISOR DIST. 3</u>	DATE <u>NOV 20 1978</u>
CONDITIONS OF APPROVAL, IF ANY:		