(Feb. 1951)				

Form 9-331a

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Lanc Office	Sai	rta.	Fø.	
Lease No	07	5331	Ž	
Unit	W.	D.	Hoath	ΠΛ

				1
SUNDRY	NOTICES'	AND	REPORTS	ON

	MINSA 1804
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.	SUBSEQUENT REPORT OF ABANDONMENT.
NOTICE OF INTENTION TO PULL OR ALTER CASING.	SUPPLEMENTARY WELL HISTORY.
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		Ferning	on, Nou Marie	o June 18,	., 19 <u>.54</u>
Well No3 is locate	ed <u>1800</u> ft. f	$\operatorname{rom}_{-}\left\{egin{smallmatrix} \mathbb{N} \\ \mathbb{S} \end{smallmatrix} ight\}$ line a	nd 1652 ft. from	$\operatorname{m}\left\{egin{array}{c} \mathbb{K} \ \mathbb{W} \end{array} ight\}$ line of sec.	17
SVA OF Sociation 17	Twp.)	Range)	Moridian)		
Manco-Managenda (Field)	***************************************	Nan Sana inty or Subdivision)		State or Territory)	
The elevation of the derrick	floor above see	level is make	٠ . ٤ .		

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was drilled to a total depth of 68 feet with rotary tools. While mining connection, boulders foll on bit. Dit and subs twisted off while attempting to from bit, leaving a figh consisting of one 124 bit and 6 feet of sais in hole. Unable to recover fish due to boulders. 125 hole was placed with 60 secks of censat filling halo to ground level with solid concrets. Finished at 5:15 P.M., Dotumber 31, 1953. Chound was restored to original contour and rig chidded 9 feet south and new hole drilled.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company Standing C11 and Gns Comeny Address Fox 187 Formington, Men Merico Title Mald Superinterdent

U. S. GOVERNMENT PRINTING OFFICE 18--8107-5