

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 065557

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☐ GAS ☒ OTHER ☐  
WELL WELL

2. NAME OF OPERATOR

PRODUCING ROYALTIES, INC

3. ADDRESS OF OPERATOR

Box 1071 LUBBOCK, TEXAS 79408

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

800 FNL 440 FEL Sec 13,  
T29N, R12W SAN JUAN Co. NM.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CARROLL-CORNELL

9. WELL NO.

S

10. FIELD AND POOL, OR WILDCAT

FULCHER-Katz PC

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 13-T29N R12W  
NM PM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5673 DF

12. COUNTY OR PARISH

SAN JUAN

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☒  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

This well has been disconnected from line.  
Operator intends to Plug & Abandon this well  
as follows:

1. Spot Cement Plug from TD 1877 to 1735
2. Pull 1" lbs & perf 4 holes @ base of Ojo Alamo
3. Squeeze Perfs w/ 50sx
4. Install P & A marker w/ 10sx

RECEIVED

JUN 9 1976

U. S. GEOLOGICAL SURVEY  
WASHINGTON, D. C.

18. I hereby certify that the foregoing is true and correct

SIGNED

Larry G. Bedford

TITLE

agent for Operator

DATE

JUNE 8, 1976

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OK