

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 065557

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Producing Royalties, Inc

3. ADDRESS OF OPERATOR

Box 1071, Lubbock, Texas 79408

4. LOCATION OF WELL. (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980 FNL & 1980 FEL, Sec 11, T29N, R12W
SAN JUAN Co. N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5730

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CARROLL CORNELL

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Fulcher Kutz PL

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 11, T29N, R12W
N.M. PM

12. COUNTY OR PARISH

SAN JUAN N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This Well has been Plugged & ABANDONED
As follows:

4-14-76 Move in equipment, Pull 1" tbg.
RAN 1" back in hole.

4-15-76 Spot 355x plug from 1989' to 1743'
Pull tbg. Perf 4 holes @ 700'
Squeeze Perfs w/ 100 SX Cement.
Left top of Cement INSIDE 7" @ 550'

4-16-76 Install P&A marker w/ 10 SX Surface Plug
Clean Up Loc.

18. I hereby certify that the foregoing is true and correct

SIGNATURE *Larry G. Bedford*

TITLE Agent for Operator

DATE 4-24-78

(This space for Federal or State office use)

APPROVED

TITLE

DATE

JUN 20 1978

R. T. McGRATH

DISTRICT ENGINEER

*See Instructions on Reverse Side