(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Mavajo	Tribal
Lesse No	1-149-	IND-765

RLL 1952

SUNDRY NOTICES AND REPORTS ON WELL

	SUBSEQUENT REPORT OF WATER SHUT-OFF
	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
	SUBSEQUENT REPORT OF ALTERING CASING
	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.
- 11	SUBSEQUENT REPORT OF ABANDONMENT
	Supplementary well history. Subsequent Secont of Dat X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

	., 19.32
Well No is located 1980 ft. from S line and 660 ft. from E line of sec	
NET OF SEE Sec. 34 31-N 17-8 No. 80-1-80	
(14 Sec. and Sec. No.) (Twp.) (Range) (Meridian)	
	.productive

The elevation of the derrick floor above sea level is 5226 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, comenting points, and all other important proposed work)

Total Depth 7093' Lime. On 5-3-52 took DST g8 from 7061' to 7093'. Tool open 2 hrs. 25 min. Gas to surface in 50 minutes. Maximum measured volume of gas 100 MCF declined to 39 MCF. Recovered 900' of fluid; first 270' Gas Out drilling and, next 630' oil and gas cut sait water. Estimated 17% oil and 83% sait water. Flowing pressure 840% to 1170%. 15 minute shut in 3.4.5.-3545%. Hydrostatic pressure 3965%.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.		
Company	The Texas Company	
Address	F. G. Box 1221	• •
Addicas	Pampa, Texas	But A Langine
	COMMITTED A COMMITTED	Dysu, vitt source
		Title set. sist. Supt.