

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | | |
|---|---|-----------|
| Name of Company OCCIDENTAL PERMIAN LTD. | Contact TONY AGUILAR | |
| Address 1017 W. Stanolind Road, Hobbs | Telephone No. (575)397-8251 | |
| Facility Name NORTH HOBBS UNIT RCF/WIB | Facility Type OIL AND GAS PRODUCTION FACILITY | |
| Surface Owner Occidental Permian LTD. | Mineral Owner HOBBS (G-SA) | Lease No. |

LOCATION OF RELEASE

| | | | | | | | | |
|------------------|---------------|------------------|---------------|---------------|------------------|---------------|----------------|---------------|
| Unit Letter H | Section 25 | Township 18-S | Range 37-E | Feet from the | North/South Line | Feet from the | East/West Line | County Lea |
|------------------|---------------|------------------|---------------|---------------|------------------|---------------|----------------|---------------|

Latitude 32°43'14.96" Longitude 103°11'59.65"

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release Gas | Volume of Release 759 MCF | Volume Recovered 0 |
| Source of Release RCF FLARE SSM EVENTS | Date and Hour of Occurrence 6/23/2015 12:23:00 PM | Date and Hour of Discovery 6/23/2015 12:23:00 PM |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? NA | |
| By Whom? NA | Date and Hour NA | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. NA | |

If a Watercourse was Impacted. Describe Fully.*
NA

RECEIVED

By OCD District 1 at 9:50 am, Jun 25, 2015

Describe Cause of Problem and Remedial Action Taken.*

Cause:

FLARED INTERMITTENTLY AT THE NORTH HOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). A-TRAIN WENT DOWN DUE TO A BAD PRO-FLOW. EOR



Remedial Action Taken:

REPLACED THE PROCENCITY SWITCH ON THE CYLINDER LOOP SYSTEM AND RESTARTED THE A-TRAIN

Describe Area Affected and Cleanup Action Taken.*

ALL GAS BURNED AT FLARE.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--|--|----------------------------|-----------------------------------|
| Signature:  | OIL CONSERVATION DIVISION | | |
| Printed Name: TONY AGUILAR | Approved by District Supervisor:  | | |
| Title: <u>HES Specialist</u> | Approval Date: <u>06/25/2015</u> | Expiration Date: <u>//</u> | |
| E-mail Address: RAYMOND_AGUILAR@OXY.COM | Conditions of Approval: <u>//</u> | | Attached <input type="checkbox"/> |
| Date: <u>6-25-15</u> Phone: (575)397-8251 | | | <u>IRP-3695</u> |

* Attach Additional Sheets If Necessary