Submit 3 copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

<u>DISTRICT I</u>	OIL CONSERVATION	N DÍVISION	WELL API NO.	
P.O. Box 1980, Hobbs, NM 88240	D. Box 1980, Hobbs, NM 88240		30-025-26000	
DISTRICT II	Santa Fe, New Mexico 87504-2088		Indicate Type of Lease	
P.O. Box Drawer DD, Artesia, NM 88210 DISTRICT III			STATE	FEE
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil / Gas Lease No. B - 15	55.1
SUNDRY NOTICES AND REPORTS ON WELLS				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI			7. Lease Name or Unit Agreement	
(FORM C-101) FOR SUCH PROPOSALS.			CENTRAL VACUUM UNIT	
1. Type of Well: OIL GAS OTHER WATER INJECTION WELL				
Name of Operator CHEVRON USA INC			8. Well No. 140	
Address of Operator			Pool Name or Wildcat VACUUM GRAYBURG SA	AN ANDRES
4. Well Location				
Unit Letter N:		H Line and 2571		_Line
Section 36	Township 17S R	ange <u>34E</u> NM	PM <u>LEA</u> (COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3988' GL				
11. Check A _l	opropriate Box to Indicate Nati	ure of Notice, Report,	or Other Data	
NOTICE OF INTENTIO	ON TO:	SU	BSEQUENT REPORT	OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	✓ ALTERING CASIN	ıG 🗀
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPE	RATION PLUG AND ABANI	DONMENT
PULL OR ALTER CASING		CASING TEST AND CEMEN	T JOB	
OTHER:		OTHER: REP	L PKR, C/O, ACIDIZE, NEW PKR &	TBG ✓
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
8-30-04: MIRU KEY #320. SET FLOW BACK TANK & FRAC TANK FOR STORAGE WATER. FILL TANKS W/10 PPG BRINE.				
8-31-04: REL PKR. LD TBG. 9-01-04: TIH W/PLUG & PKR. SET PLUG @ 4078. REL PKR. DISPL W/70 BBLS BRINE. CHART TEST CSG FR SURFACE TO 4078 TO 960 PSIG				
FOR 30 MINS. OK.				
9-02-04: REL RBP. WENT ON SLIGHT VAC. TIH W/MILL, DC'S & 138 JTS 2 3/8" TBG. TAG @ 4405. DRY DRILL FR 4405-4550. TIGHT SPOTS @ 4405-4550. DRILLED @ 4550. COULD NOT MAKE ANY HOLE.				
9-03-04: PU 146 JTS 2 3/8" TBG, TAG @ 4550, SET DN 10 PTS ON BLOCK, PU MILL, DC'S & 142 JTS TBG, TAG @ 4550, DRY DRILL ON BAD				
SPOT. PUMP 2 1/2" BPM. DRILL FR 4550-4552. FELL THRU. DRILL THRU TIGHT SPOTS FR 4552-4683. STRING LOCKED DN @ 4683. WORK STRING FREE.				
9-07-04: TIH W/PKR & SET @ 4075. 9-08-04: ACIDIZE PERFS W/4000 GALS 15% ACID IN 4 STAGES. REL PKR.				
9-09-04: ACIDIZE PERFS W/4000 GALS 19% ACID IN 4 STAGES. REL PKR. 9-09-04: WORK MILL THRU BAD SPOT @ 4645-4653. WASH DN TO 4683. TIH W/PKR & PUMP OUT PLUG & 131 JTS 2 3/8" TBG. PKR SET @ 4080.				
0.10.04: CHART TEST CSC @ 525 BSI FOR 25 MINS. CAINED 5 BSI TO 540 BSI BLOW BLIND OUT BLUG MISSO BSI BIG BOARD				
THURST STO		•	15161778	79.
			7 PLOG W/900 PSI. RIG DOW	190
			/ No.	* 1
			(E) SEP 11.	i i
			lo huzivi	<u>-</u> U
			Hobbs OCD	
			1000	
I hereby certify that the information above is true and complete	the best of my knowledge and belief.		22 . 11.15	<u> </u>
SIGNATURE	Yake TITLE Regul	atory Specialist	DATE9,	/14/2004
TYPE OR PRINT NAME DE	enise Leake		Telephone No.	915-687-7375
(This space for State Use)				

APPROVED APPROVAL, IF ANY:

