Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
District 1 Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-40040
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410 Sonto Eo. NIM 87505	STATE FEE
District IV 1220 S St Trancis Dr , Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Quail Ridge 32 State
1. Type of Well: Oil Well  Gas Well  Other	8. Well Number
	003
2. Name of Operator	9. OGRID Number
Cimarex Energy Co. of Colorado	162683
3. Address of Operator	10. Pool name or Wildcat
600 N. Marienfeld St., Ste. 600; Midland, TX 79701	Apache Ridge; Bone Spring
4. Well Location	7
SHL Unit Letter 1 : 1650 feet from the South line and 330	feet from the East line
	-
Section 32 Township 195 Range 34E NMPM	CountyLea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3661 GR	
Pit or Below-grade Lank Application  or Closure	<b>3.20</b>
	D:
Pit type Depth to Groundwater Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: Below-Grade Tank: Volume bbls; Cor	struction Material
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
	SEQUENT REPORT OF:
- LPERFORM REMEDIAL WORK - LL - PLUG AND ABANDON - LLI REMEDIAL WOR	RK □ ALTERING CASING □
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WOR TEMPORARILY ABANDON  CHANGE PLANS  COMMENCE DR	<del>_</del>
TEMPORARILY ABANDON	ILLING OPNS PANDA
TEMPORARILY ABANDON	ILLING OPNS  P AND A  T
TEMPORARILY ABANDON	ILLING OPNS
TEMPORARILY ABANDON	ILLING OPNS  P AND A
TEMPORARILY ABANDON	ILLING OPNS  P AND A
TEMPORARILY ABANDON	ILLING OPNS PAND A Completion Completion ve pertinent dates, including estimated date of ellbore diagram of proposed completion or
TEMPORARILY ABANDON	ILLING OPNS PAND A Completion Completion or
TEMPORARILY ABANDON	ILLING OPNS PAND A Completion Completion Completion or Com
TEMPORARILY ABANDON	ILLING OPNS PAND A Completion Completion Completion or Com
TEMPORARILY ABANDON	ILLING OPNS PAND A Completion Completion Completion or PAND A Completion With a completion or Completion or Parallel State of Completion or Co
TEMPORARILY ABANDON	Completion Completion or Compl
TEMPORARILY ABANDON	ILLING OPNS PAND A Completion Completion Completion or Panal Representation of
TEMPORARILY ABANDON	Completion Completion or Compl
TEMPORARILY ABANDON	ILLING OPNS PAND A Completion Completion Completion or Panal Representation of
TEMPORARILY ABANDON	Completion Completion or Compl
TEMPORARILY ABANDON CHANGE PLANS CASING/CEMEN PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER.  13. Describe proposed or completed operations. (Clearly state all pertinent details, and girstarting any proposed work). SEE RULE 1103. For Multiple Completions. Attach we recompletion.  O7-27-11 Perf Bone Spring 14643-15334 6 spf, 40 holes. Frac with 206,241 gal 2 Set CBP @ 14528. Perf Bone Spring 13708-14412 6 spf, 40 holes. Frac 224,486# 20/40 CRC Sand. Set CBP @ 13592. Perf Bone Spring 12772 gal 20# Borate XL & 233,467# 20/40 CRC Sand.  O7-28-11 Set CBP @ 12642. Perf Bone Spring 11836-12540 6 spf, 40 holes. Frac 248,595# 20/40 CRC Sand. Set CBP @ 11710. Perf Bone Spring 10900 gal 20# Borate XL & 276,754# 20/40 CRC Sand.  O8-12-11 Began drilling out CBPs.  O8-13-11 Finished DO CBPs and CO to PBTD @ 15340.  Installed production tubing string: 2.875" 6.5# L80 EUE @ 10335. Also	Completion Completion or Compl
TEMPORARILY ABANDON	Completion Completion or Compl
TEMPORARILY ABANDON CHANGE PLANS CASING/CEMEN PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER.  13. Describe proposed or completed operations. (Clearly state all pertinent details, and girstarting any proposed work). SEE RULE 1103. For Multiple Completions. Attach we recompletion.  O7-27-11 Perf Bone Spring 14643-15334 6 spf, 40 holes. Frac with 206,241 gal 2 Set CBP @ 14528. Perf Bone Spring 13708-14412 6 spf, 40 holes. Frac 224,486# 20/40 CRC Sand. Set CBP @ 13592. Perf Bone Spring 12772 gal 20# Borate XL & 233,467# 20/40 CRC Sand.  O7-28-11 Set CBP @ 12642. Perf Bone Spring 11836-12540 6 spf, 40 holes. Frac 248,595# 20/40 CRC Sand. Set CBP @ 11710. Perf Bone Spring 10900 gal 20# Borate XL & 276,754# 20/40 CRC Sand.  O8-12-11 Began drilling out CBPs.  O8-13-11 Finished DO CBPs and CO to PBTD @ 15340.  Installed production tubing string: 2.875" 6.5# L80 EUE @ 10335. Also	Completion Completion or Compl
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER.  13. Describe proposed or completed operations. (Clearly state all pertinent details, and gister starting any proposed work). SEE RULE 1103. For Multiple Completions. Attach we recompletion.  O7-27-11 Perf Bone Spring 14643-15334 6 spf, 40 holes. Frac with 206,241 gal 22 Set CBP @ 14528. Perf Bone Spring 13708-14412 6 spf, 40 holes. Frac 224,486# 20/40 CRC Sand. Set CBP @ 13592. Perf Bone Spring 12772 gal 20# Borate XL & 233,467# 20/40 CRC Sand.  O7-28-11 Set CBP @ 12642. Perf Bone Spring 11836-12540 6 spf, 40 holes. Frac 248,595# 20/40 CRC Sand. Set CBP @ 11710. Perf Bone Spring 10900 gal 20# Borate XL & 276,754# 20/40 CRC Sand.  O8-12-11 Began drilling out CBPs.  O8-13-11 Finished DO CBPs and CO to PBTD @ 15340.  O8-16-11 Installed production tubing string: 2.875" 6.5# L80 EUE @ 10335. Also 08-17-11 Turned over to production.	Completion Completion or Compl
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER.  13. Describe proposed or completed operations. (Clearly state all pertinent details, and gister starting any proposed work). SEE RULE 1103. For Multiple Completions. Attach we recompletion.  O7-27-11 Perf Bone Spring 14643-15334 6 spf, 40 holes. Frac with 206,241 gal 22 Set CBP @ 14528. Perf Bone Spring 13708-14412 6 spf, 40 holes. Frac 224,486# 20/40 CRC Sand. Set CBP @ 13592. Perf Bone Spring 12772 gal 20# Borate XL & 233,467# 20/40 CRC Sand.  O7-28-11 Set CBP @ 12642. Perf Bone Spring 11836-12540 6 spf, 40 holes. Frac 248,595# 20/40 CRC Sand. Set CBP @ 11710. Perf Bone Spring 10900 gal 20# Borate XL & 276,754# 20/40 CRC Sand.  O8-12-11 Began drilling out CBPs.  O8-13-11 Finished DO CBPs and CO to PBTD @ 15340.  O8-16-11 Installed production tubing string: 2.875" 6.5# L80 EUE @ 10335. Also 08-17-11 Turned over to production.	Completion Completion or Compl
TEMPORARILY ABANDON	ILLING OPNS P AND A Completion Completion Completion or P And Completion or P And A Completion or Co
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN OTHER.  13. Describe proposed or completed operations. (Clearly state all pertinent details, and gister starting any proposed work). SEE RULE 1103. For Multiple Completions. Attach we recompletion.  O7-27-11 Perf Bone Spring 14643-15334 6 spf, 40 holes. Frac with 206,241 gal 22 Set CBP @ 14528. Perf Bone Spring 13708-14412 6 spf, 40 holes. Frac 224,486# 20/40 CRC Sand. Set CBP @ 13592. Perf Bone Spring 12772 gal 20# Borate XL & 233,467# 20/40 CRC Sand.  O7-28-11 Set CBP @ 12642. Perf Bone Spring 11836-12540 6 spf, 40 holes. Frac 248,595# 20/40 CRC Sand. Set CBP @ 11710. Perf Bone Spring 10900 gal 20# Borate XL & 276,754# 20/40 CRC Sand.  O8-12-11 Began drilling out CBPs.  O8-13-11 Finished DO CBPs and CO to PBTD @ 15340.  O8-16-11 Installed production tubing string: 2.875" 6.5# L80 EUE @ 10335. Also 08-17-11 Turned over to production.	Completion Completion Completion or P AND A Completion Completion or P Borate XL & 248,348# 20/40 CRC Sand. With 168,264 gal 20# Borate XL & -13476 6 spf, 40 holes. Frac with 177,054 with 183,796 gal 20# Borate XL & -11604 6 spf, 40 holes. Frac with 194,258 P installed ESP from JW Enterprise.
TEMPORARILY ABANDON	Completion Completion Completion or P AND A Completion Completion or P Borate XL & 248,348# 20/40 CRC Sand. With 168,264 gal 20# Borate XL & -13476 6 spf, 40 holes. Frac with 177,054 with 183,796 gal 20# Borate XL & -11604 6 spf, 40 holes. Frac with 194,258 P installed ESP from JW Enterprise.
TEMPORARILY ABANDON	Completion Completion Completion or P AND A Completion Completion or P Borate XL & 248,348# 20/40 CRC Sand. With 168,264 gal 20# Borate XL & -13476 6 spf, 40 holes. Frac with 177,054 with 183,796 gal 20# Borate XL & -11604 6 spf, 40 holes. Frac with 194,258 P installed ESP from JW Enterprise.
TEMPORARILY ABANDON	ILLING OPNS