

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N French Dr, Hobbs, NM 88240
District II - (575) 748-1283
811 S First St, Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd, Aztec, NM 87410
District IV - (505) 476-3460
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

HOBBS OCD

OIL CONSERVATION DIVISION

OCT 05 2012

220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. ☒ 30-025-36046
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator Occidental Permian Ltd.		6. State Oil & Gas Lease No.
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323		7. Lease Name or Unit Agreement Name Hobbs Deep A
4. Well Location Unit Letter <u>P</u> : <u>990</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>East</u> line Section <u>13</u> Township <u>18S</u> Range <u>37E</u> NMPM <u>Lea</u> County <u>Seven Rivers</u>		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc) 3671' GL		9. OGRID Number: 157984
		10. Pool name or Wildcat Hobbs (G/SA) Wildcat; Tubbs; Drinkard; Abo

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ Rule 19.15.25.14
Set CIBP, RBP or Packer within 100 feet of uppermost
perforations or open hole Pressure test to 500 psi for 30 minutes with
a pressure drop of not greater than 10% over a
30 minute period
COMMENCE DRILLING OR REPAIRS ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) POOH with prod equip.
- 2) Clean out to 3234'
- 3) Set CIBP at 3185'. Cap with 35' of cmt. → Circ w/ PKR. fluid
- 4) Run MIT
- 5) Well is TA

**Condition of Approval: notify
OCD Hobbs office 24 hours
prior of running MIT Test & Chart**

Conditions of Approval: The Operator shall give the OCD District office 24 hours notice before work begins

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve Snead TITLE Lift Specialist DATE 9/26/12

Type or print name Steve Snead E-mail address: steve_snead@oxy.com PHONE: 806-592-6312
For State Use Only

APPROVED BY: [Signature] TITLE Dist. Mgr. DATE 10-17-2012

Conditions of Approval: Notify OCD District office 24 hours prior to running the TA Pressure Test.

OCT 18 2012

OCT 16 2012

RECEIVED

Wellbore Diagram : HBS DP A-1

