

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

1301 W. Grand Ave, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO.

30-025-07487

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

NORTH HOBBS (G/SA) UNIT
Section 30

8. Well No. 141

9. OGRID No. 157984

10. Pool name or Wildcat HOBBS (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)

1. Type of Well:

Oil Well ☐

Gas Well ☐

Other T&A'd

2. Name of Operator

Occidental Permian Ltd.

3. Address of Operator

1017 W. Stanolind Rd., HOBBS, NM 88240

505/397-8200

4. Well Location

Unit Letter M : 990 Feet From The SOUTH 990 Feet From The WEST Line

Section 30

Township 18-S

Range 38-E

NMPM

LEA

County

11. Elevation (Show whether DF, RKB, RT GR, etc.)

3651' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water

Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material

12.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG & ABANDONMENT ☐

PULL OR ALTER CASING ☐

Multiple Completion ☐

CASING TEST AND CEMENT JOB ☐

OTHER: _____

OTHER: Return to Production, Sqz, Acid Treat

☒

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion:

1. RUPU. Drill out CIBP @3956'.
2. Sqz Perfs 4006-4114' w/400 sx Pre + cmt w/3% CaCl. Clean out to PBTD @4269'.
3. Perforate the following intervals; 4213-25 and 4258-65, using 2 spf, 120 deg spiral ph. (42 holes).
4. Stimulate new perfs w/1100 g 15% NEFE HCL acid.
5. RIH Reda ESP equipment on 127 jts 2-7/8" tbg w/drain valve. Intake set @4177'.
6. Install QCI wellhead connection..
7. RDPU. Clean Location.

Rig Up Date: 03/18/2005

Rig Down Date: 03/29/2005

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or

closed according to NMOC guidelines ☐ , a general permit ☐

or an (attached) alternative OCD-approved plan ☐

SIGNATURE

Robert Gilbert

TITLE Workover Completion Specialist

DATE 04/01/2005

TYPE OR PRINT NAME Robert Gilbert

E-mail address: robert_gilbert@oxy.com

TELEPHONE NO. 505/397-8206

For State Use Only

APPROVED BY

[Signature]

TITLE

PETROLEUM ENGINEER

DATE

JUN 27 2005

CONDITIONS OF APPROVAL IF ANY: