Office	ppropriate District	State of New Mexico	Form C-103
District I		Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Ho	obbs, NM 88240		WELL API NO.
District II		OIL CONCEDIATION DIVIGION	30-025- 94250- 34850
1301 W. Grand Ave., A	Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., A	Aztec NM 97410	1220 South St. Francis Dr.	
District IV	AZICC, INIVI 6/410	Santa Fe, NM 87505	STATE FEE x
1220 S. St. Francis Dr.	, Santa Fe, NM	•	6. State Oil & Gas Lease No.
87505			LC-031740-B
	SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS F	FORM FOR PROPO	DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Eunice Monument South Unit
PROPOSALS.)	OIR. USE "APPLI	CATION FOR PERMIT" (FORM C-101) FOR SUCH	
1 ′	0.1337 11 🔲	S. W. I. C	8. Well Number 711
1. Type of Well:	~	Gas Well Other	o. Won Ivaniooi 711
2. Name of Opera			9. OGRID Number 4323
		ENERGY INC.	
3. Address of Ope	erator 200 LC	ORAINE	10. Pool name or Wildcat
	MIDL.	AND, TX 79701	Eunice Monument; Grayburg-San Andres
4. Well Location	***************************************		
Unit Lette	D	1210 6 46 4	
1	er <u>P</u>	1310 feet from theSOUTH line a	nd 200 feet from the EAST
line			
Section	9	Township 21 S Range 36	E NMPM County LEA
		11. Elevation (Show whether DR, RKB, RT, GR,	
		11. Dievation (Snow Whether DK, 100), K1, OK,	etc.)
Pit or Below-grade Tar	nk Application 🗍 c	or Closure	
Pit type	Depth to Groundw	aterDistance from nearest fresh water well	Distance from nearest surface water
			_
Pit Liner Thickness:	mil	Below-Grade Tank: Volumebbls	Construction Material
Pit Liner Thickness:			Construction Material
Pit Liner Thickness:		Below-Grade Tank: Volume bbls Appropriate Box to Indicate Nature of Not	
	12. Check A	Appropriate Box to Indicate Nature of Not	ce, Report or Other Data
NC	12. Check A	Appropriate Box to Indicate Nature of Not	ce, Report or Other Data UBSEQUENT REPORT OF:
NC PERFORM REMEI	12. Check ADTICE OF INDIAL WORK	Appropriate Box to Indicate Nature of Not ITENTION TO: PLUG AND ABANDON REMEDIAL V	UBSEQUENT REPORT OF: VORK ALTERING CASING
NC PERFORM REMEI TEMPORARILY AS	12. Check ADTICE OF INDIAL WORK BANDON	Appropriate Box to Indicate Nature of Not ITENTION TO: PLUG AND ABANDON REMEDIAL V COMMENCE	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A
NC PERFORM REMEI	12. Check ADTICE OF INDIAL WORK BANDON	Appropriate Box to Indicate Nature of Not ITENTION TO: PLUG AND ABANDON REMEDIAL V	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A
PERFORM REMEI TEMPORARILY AS PULL, OR ALTER O	12. Check ADTICE OF INDIAL WORK BANDON	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CASING/CEN	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A
PERFORM REMEITEMPORARILY AND PULL, OR ALTER O	12. Check ADTICE OF INDIAL WORK BANDON CASING	Appropriate Box to Indicate Nature of Not ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL OTHER:	CCE, Report or Other Data UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB
PERFORM REMEI TEMPORARILY AS PULL, OR ALTER O OTHER:	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON	UBSEQUENT REPORT OF: /ORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB
PERFORM REMEITEMPORARILY AS PULL, OR ALTER OF THER: 13. Describe prof starting a	12. Check A DTICE OF IN DIAL WORK BANDON CASING Toposed or comp any proposed wo	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON	UBSEQUENT REPORT OF: /ORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB
PERFORM REMEI TEMPORARILY AS PULL, OR ALTER O OTHER:	12. Check A DTICE OF IN DIAL WORK BANDON CASING Toposed or comp any proposed wo	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON	CCE, Report or Other Data UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF THER: 13. Describe prof starting as or recomplete.	12. Check ADTICE OF INDIAL WORK BANDON CASING COMPANY Proposed or company proposed we etion.	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A DRILLING OPNS. ALTERING CASING ALTERING CASING DRILLING OPNS. P AND A DRILLING OPNS. ALTERING CASING DRILLING OPNS. P AND A DRILLING OPNS. P AND A DRILLING OPNS. ALTERING CASING DRILLING CASING CA
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF THER: 13. Describe prof starting as or recomplete.	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING Company proposed or company proposed we etion.	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. PAND A DRILLING OPNS. ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING DRILLING OPNS. PAND A DEVILOR AND ALTERING CASING DRILLING OPNS. PAND A DEVILOR AND ALTERING CASING DRILLING CASING CA
PERFORM REMEITEMPORARILY AS PULL, OR ALTER OF STARTING ST	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING Company proposed or company proposed we etion.	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. PAND A DRILLING OPNS. ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING DRILLING OPNS. PAND A DEVILOR AND ALTERING CASING DRILLING OPNS. PAND A DEVILOR AND ALTERING CASING DRILLING CASING CA
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STARTING AS OF recomple	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING COMPANY Proposed or company proposed we etion.	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. PAND A DRILLING OPNS. ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING DRILLING OPNS. PAND A DEVILOR AND ALTERING CASING DRILLING OPNS. PAND A DEVILOR AND ALTERING CASING DRILLING CASING CA
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STARTING AS OF recomple	12. Check A DTICE OF IN DIAL WORK BANDON CASING Toposed or company proposed wo etion. 20/2005 121/2005 122/2005 1	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. PAND A DRILLING OPNS. ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING DRILLING OPNS. PAND A DEVILOR AND ALTERING CASING DRILLING OPNS. PAND A DEVILOR AND ALTERING CASING DRILLING CASING CA
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STARTING AS OF recomple	12. Check A DTICE OF IN DIAL WORK BANDON CASING Troposed or company proposed wo etion. 20/2005 21/2005 22/2005 3	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB And give pertinent dates, including estimated date attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes)
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STARTING AS OF recomple	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING COMPANY proposed or company proposed we etion.	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS COMMENCE CASING/CEM OTHER:	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB And give pertinent dates, including estimated date attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes)
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STARTING AS OF recomple	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING COMPANY proposed or company proposed we etion.	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CASING/CEM OTHER: Seleted operations. (Clearly state all pertinent details ork). SEE RULE 1103. For Multiple Completions MIRU, NDWH, NU BOP, POOH, TST TBG – YERU, Log & Perf Grayburg perfs: 3724'-3726' (RIH to 3772', ACD w/100 gals 15% HCL NEFE 3654' set PKR – broke dwn perfs at 3500 psig, ACD new perfs 3724-3738' w/1500 gals acd, drop Balled out w/35 BS at perfs	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB And give pertinent dates, including estimated date attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes)
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STARTING AS OF recomple	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING COMPANY proposed or company proposed we etion.	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CASING/CEM OTHER:	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB And give pertinent dates, including estimated date attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes)
PERFORM REMEITEMPORARILY AE PULL OR ALTER OF STARTING & or recomple	12. Check ADTICE OF INDIAL WORK BANDON CASING CASIN	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CASING/CEM OTHER:	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB And give pertinent dates, including estimated date attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes)
PERFORM REMEITEMPORARILY AE PULL OR ALTER OF STARTING & OT RECOMPLE 13. Describe prof starting & OT recomple 7/2 7/2 7/2	12. Check ADTICE OF INDIAL WORK BANDON CASING CASIN	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB And give pertinent dates, including estimated date attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes)
PERFORM REMEITEMPORARILY AE PULL OR ALTER OF STARTING & OT RECOMPLE 13. Describe prof starting & OT recomple 7/2 7/2 7/2	12. Check ADTICE OF INDIAL WORK BANDON CASING CASIN	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CASING/CEM OTHER:	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB And give pertinent dates, including estimated date attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes)
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STARTING SOFT OF STARTING SOF	12. Check ADTICE OF INDIAL WORK BANDON CASING CASIN	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CASING/CEM OTHER:	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB , and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes) ped 3 ball sealers every 2 bbls last 1000 gals
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STARTING SOFT OF STARTING SOF	12. Check ADTICE OF INDIAL WORK BANDON CASING CASIN	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CASING/CEM OTHER: OTHER: Oleted operations. (Clearly state all pertinent details ork). SEE RULE 1103. For Multiple Completions MIRU, NDWH, NU BOP, POOH, TST TBG – YERU, Log & Perf Grayburg perfs: 3724'-3726' (RIH to 3772', ACD w/100 gals 15% HCL NEFE 3654' set PKR – broke dwn perfs at 3500 psig, ACD new perfs 3724-3738' w/1500 gals acd, drop: Balled out w/35 BS at perfs MAX trtng psi = 4000 psig, 5" SI press –vac. SWB LOAD TBG w/12 BW, ok. RDPU above is true and complete to the best of my know	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB , and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes) ped 3 ball sealers every 2 bbls last 1000 gals
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STARTING SOFT OF STARTING SOF	12. Check ADTICE OF INDIAL WORK BANDON CASING CASIN	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CASING/CEM OTHER:	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB , and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes) ped 3 ball sealers every 2 bbls last 1000 gals
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STARTING SOFT OF STARTING SOF	12. Check ADTICE OF INDIAL WORK BANDON CASING CASIN	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL OTHER: Othe	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB , and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes) Deed 3 ball sealers every 2 bbls last 1000 gals ledge and belief. I further certify that any pit or below- it or an (attached) alternative OCD-approved plan
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STARTING SOFT OF STARTING SOF	12. Check ADTICE OF INDIAL WORK BANDON CASING CASIN	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CASING/CEM OTHER: OTHER: Oleted operations. (Clearly state all pertinent details ork). SEE RULE 1103. For Multiple Completions MIRU, NDWH, NU BOP, POOH, TST TBG – YERU, Log & Perf Grayburg perfs: 3724'-3726' (RIH to 3772', ACD w/100 gals 15% HCL NEFE 3654' set PKR – broke dwn perfs at 3500 psig, ACD new perfs 3724-3738' w/1500 gals acd, drop: Balled out w/35 BS at perfs MAX trtng psi = 4000 psig, 5" SI press –vac. SWB LOAD TBG w/12 BW, ok. RDPU above is true and complete to the best of my know	UBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB department dates, including estimated date Attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes) Deed 3 ball sealers every 2 bbls last 1000 gals dedge and belief. I further certify that any pit or below- tit or an (attached) alternative OCD-approved plan
PERFORM REMEIT TEMPORARILY AS PULL OR ALTER OF STARTING SOFT OF STARTING S	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING COMPANY proposed or company proposed we etion. 20/2005 12/2005 12/2005 13/2005 14/2005 15/2005 1	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL OTHER: OTHER: Seleted operations. (Clearly state all pertinent details ork). SEE RULE 1103. For Multiple Completions MIRU, NDWH, NU BOP, POOH, TST TBG — YERU, Log & Perf Grayburg perfs: 3724'-3726' (RIH to 3772', ACD w/100 gals 15% HCL NEFE 3654' set PKR — broke dwn perfs at 3500 psig, ACD new perfs 3724-3738' w/1500 gals acd, drop: Balled out w/35 BS at perfs MAX trtng psi = 4000 psig, 5" SI press —vac. SWB LOAD TBG w/12 BW, ok. RDPU above is true and complete to the best of my know closed according to NMOCD guidelines n a general perm TITLE: PRODUCTION	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB , and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes) Ded 3 ball sealers every 2 bbls last 1000 gals ledge and belief. I further certify that any pit or below- it or an (attached) alternative OCD-approved plan ANALYST DATE: 08-03-2005
PERFORM REMEIT TEMPORARILY AS PULL OR ALTER OF STARTING SOFT OF STARTING S	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING COMPANY proposed or company proposed we etion. 20/2005 12/2005 12/2005 13/2005 14/2005 1	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL OTHER: OTHER: Seleted operations. (Clearly state all pertinent details ork). SEE RULE 1103. For Multiple Completions MIRU, NDWH, NU BOP, POOH, TST TBG — YERU, Log & Perf Grayburg perfs: 3724'-3726' (RIH to 3772', ACD w/100 gals 15% HCL NEFE 3654' set PKR — broke dwn perfs at 3500 psig, ACD new perfs 3724-3738' w/1500 gals acd, drop: Balled out w/35 BS at perfs MAX trtng psi = 4000 psig, 5" SI press —vac. SWB LOAD TBG w/12 BW, ok. RDPU above is true and complete to the best of my know closed according to NMOCD guidelines REDPU TITLE: PRODUCTION	UBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB C, and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes) Ded 3 ball sealers every 2 bbls last 1000 gals Ded 3 ball sealers every 2 bbls last 1000 gals Ded 3 ball sealers every 2 bbls last 1000 gals Ded 3 ball sealers every 2 bbls last 1000 gals Ded 3 ball sealers every 2 bbls last 1000 gals Ded 3 ball sealers every 2 bbls last 1000 gals Ded 3 ball sealers every 2 bbls last 1000 gals Ded 3 ball sealers every 2 bbls last 1000 gals Ded 3 ball sealers every 2 bbls last 1000 gals Ded 3 ball sealers every 2 bbls last 1000 gals
PERFORM REMEIT TEMPORARILY AS PULL OR ALTER OF STARTING SOFT OF STARTING S	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING COMPANY proposed or company proposed we etion. 20/2005 12/2005 12/2005 13/2005 14/2005 1	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CASING/CEM OTHER:	UBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB , and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes) Ded 3 ball sealers every 2 bbls last 1000 gals dedge and belief. I further certify that any pit or below- it or an (attached) alternative OCD-approved plan ANALYST DATE: 08-03-2005 By.com Telephone No. 432-620-6714
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STATE OF STA	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING COMPANY proposed or company proposed we etion. 20/2005 12/2005 12/2005 13/2005 14/2005 1	Appropriate Box to Indicate Nature of Not. ITENTION TO:	UBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB , and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes) Ded 3 ball sealers every 2 bbls last 1000 gals dedge and belief. I further certify that any pit or below- it or an (attached) alternative OCD-approved plan ANALYST DATE: 08-03-2005 By.com Telephone No. 432-620-6714
PERFORM REMEIT TEMPORARILY AS PULL OR ALTER OF STATE OF S	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING COMPANY proposed or company proposed we etion. 20/2005 12/2005 12/2005 13/2005 14/2005 14/2005 15/2005 1	Appropriate Box to Indicate Nature of Not. ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CASING/CEM OTHER:	UBSEQUENT REPORT OF: VORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB , and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes) Ded 3 ball sealers every 2 bbls last 1000 gals ledge and belief. I further certify that any pit or below- it or an (attached) alternative OCD-approved plan ANALYST DATE: 08-03-2005
PERFORM REMEITEMPORARILY AS PULL OR ALTER OF STATE OF STA	12. Check ADTICE OF INDIAL WORK BANDON CASING CASING COMPANY proposed or company proposed we etion. 20/2005 12/2005 12/2005 13/2005 14/2005 14/2005 15/2005 1	Appropriate Box to Indicate Nature of Not. ITENTION TO:	UBSEQUENT REPORT OF: ORK ALTERING CASING DRILLING OPNS. P AND A MENT JOB , and give pertinent dates, including estimated date: Attach wellbore diagram of proposed completion LLOWBAND 2', 6 holes), 3732-4738' (6', 18 holes) Ded 3 ball sealers every 2 bbls last 1000 gals dedge and belief. I further certify that any pit or below- it or an (attached) alternative OCD-approved plan ANALYST DATE: 08-03-2005 By.com Telephone No. 432-620-6714