

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised March 25, 1999

DISTRICT I
1625 N. French Dr., Hobbs, NM 88240
DISTRICT II
811 South First, Artesia NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410
DISTRICT IV
2040 South Pacheco, Sante Fe, NM 87505

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-23567

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
8055

B-1520

7. Lease Name or Unit Agreement Name

North Vacuum Abo Unit

8. Well No.

144

9. Pool name or Wildcat
Vacuum;Abo, North

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

Oil ☐
Well

Gas ☐
Well

Other **Injection**

2. Name of Operator

Exxon Mobil Corporation

3. Address of Operator **P.O. Box 4358**

Houston

TX 77210-4358

4. Well Location

Unit Letter **P** : **660** Feet From The **East** Line and **460** Feet From The **South** Line
Section **15** Township **17S** Range **34E** NMPH **Lea** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
GR 4046'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion)

Filed to report work performed to repair tubing. MIT chart ran 5-15-03, witnessed by NM OCD rep Johnny Robinson.
Original chart with Johnny Robinson.

4/10/03 Drive crew & rig to location. Wait on rig mat. Spot rig. Hold safety meeting. RU WSU. Shut down. Unload pipe rack. Unload tubing. SDFN

4/11/03 Drive crew to location. Hold safety meeting. Inspect rig. Check H2S monitor. Bleed well down. Remove WH tree. Worked w/ donut. NU BOP. Worked w/ wellhead, donut out. Unset packer. RU pump truck. Test BOP, tested good. Pumped 90 bbls down tbg. Laid down 8 jts. Close well in. SDFWE

4/14/03 Drive crew to location. Inspect rig. Check H2S monitor. RU pump & vac trucks. Circulate well. RU pump & vac trucks. LD 248 Jts tbg. POOH w/ 19 stands. LD packer. RIH w/ kill string. Close well in. SDFN

SEE ATTACHMENT FOR ADDITIONAL REMARKS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tiffany A. Stebbins TITLE Staff Office Assistant

DATE 05/19/2003

TYPE OR PRINT NAME Tiffany A. Stebbins

TELEPHONE NO. (713) 431-1207

(This space for State Use)

APPROVED BY May W. Wink

CO FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

MAY 21 2003

*Submit 3 Copies
to Appropriate
District Office

ATTACHMENT

State of New Mexico

Energy, Minerals and Natural Resources Department

Form C-103
Revised March 25, 1999

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

811 South First, Artesia NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV

2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-23567

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

8055

B-1520

7. Lease Name or Unit Agreement Name

North Vacuum Abo Unit

8. Well No.

144

9. Pool name or Wildcat

Vacuum;Abo, North

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

Oil

Well ☐

Gas

Well ☐

Other **Injection**

2. Name of Operator

Exxon Mobil Corporation

3. Address of Operator **P.O. Box 4358**

Houston

TX 77210-4358

4. Well Location

Unit Letter **P** : **660** Feet From The **East** Line and **460** Feet From The **South** Line

Section **15**

Township **17S**

Range **34E**

NMPH

Lea

County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

GR 4046'

Additional Remarks

4/15/03 Drive crew to location. Hold safety meeting. Inspect rig, check H2S monitor. Open BOP. Finished LD tbg. PU On-Off tool & pkr. Tally tbg. PU & RIH w/ 100 Jts tbg. Shut well in. SDFN

4/16/03 Drive crew to location. Hold safety meeting. Inspect rig, check H2S monitor. Check pressure on well. Open BOP. Begin PU tbg. Backside began running over. WO vac truck. RU vac truck. Finished PU tbg. Latch onto packer. RU pump truck. L & T tbg, 500 # PSI, OK. Circulate well w/ packer fluid. Latch onto packer. ND BOP. Flange up wellhead. RU pump to backside to test packer, OK. RD pump truck. Close well in. SDFN

4/17/03 Drive crew to location. Hold safety meeting. Inspect rig, check H2S monitor. Wait on orders. Flange up wellhead. RD WSU. Clean location. MO WSU.

Permanent Baker NB packer @ 8609'. Copy of passing MIT chart attached.

