## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004


FILE IN TRIPLICATE OIL	CONSERVATION DIVISION	Revised 5-27-2004
DISTRICT I 1625 N. French Dr., Hobbs, NM 8824010BBS OCD	1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-05466
DISTRICT II	,	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88219UL 2 5 2013		STATE X FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)		Section 23
Type of Well: Oil Well X Gas Well Other		8. Well No. 421
Name of Operator     Occidental Permian Ltd.		9. OGRID No. 157984
3. Address of Operator		10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323		<u> </u>
Unit Letter H : 1650 Feet From The North Line and 330 Feet From The East Line		
Section 23 Townshi	p 18-S Range 37-1	E NMPM Lea County
11. Elevation (S 3660.8 GL	Show whether DF, RKB, RT GR, etc.)	
Pit or Below-grade Tank Application or Closure		
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABA	NDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPN		NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Comple	tion CASING TEST AND CEME!	NT JOB
THER:OTHER:OEepen/Liner/OAP/AT		er/OAP/AT X
<ol> <li>Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> <li>RUPU &amp; RU.</li> <li>RU wire line &amp; perforate tubing @3868'. RD wire line.</li> <li>ND wellhead/NU BOP.</li> </ol>		
4. POOH & lay down ESP equipment.		
5. RIH w/bit and drill collars. Tag @4285'. Clean out formation from 4285-4305'. Drill out new formation from 4305-4360'. New TD. POOH w/bit & drill collars. Circulate clean.		
6. RIH w/4-1/2" FJ liner to TD @4360. RU HES & pump 25 sacks of .2% Class C cement. Displace w/25 bbl fresh water. RD HES. 7. RIH w/bit. Tagged TOL @3894. No cement on top. Tested and leaked. POOH w/bit.		
8. RIH w/CICR set @3826'.		
<ol> <li>RU pump truck &amp; pump 122 bbl of .2% Super CBL cement into liner. Stung out 22 bbl, got 98 bbl in liner. RD pump truck.</li> <li>RIH w/bit. Tag @3826'. NU stripper head &amp; power swivel. Drill on CICR 3830-3831' and cement from 3831-4363'. Circ clean.</li> <li>***see attached sheet for additional data***</li> </ol>		
I hereby certify that the information above is true and complete to		
constructed or closed according to NMOCD guidelines , a gene	ral permit or an (attached) alternativ	re OCD-approved
SUCHA EURE MANA LA CAL	plan	
SIGNATURE TYPE OF PRINT NAME AND A STATE OF PRINT NAME	TITLE Administrative	-
TYPE OR PRINT NAME Mendy A. Johnson For State Use Only	E-mail address: mendy_johnson@oxy.com	TELEPHONE NO. 806-592-6280
APPROVED BY	TITLE DIST, NO	DATE 7-31-2013
CONDITIONS OF APPROVAL IF ANY	THE SOLL STATE	DATE!

## NHU 23-421 API 30-025-05466

- 11. ND stripper head and power swivel. POOH w/bit.
- 12. RU wire line & run CNL/CCL/GR log from 4355-3355'. RD wire line.
- 13. RU wire line & perforate well @4260-64', 4268-71', 4277-84', 4320-28', 4332-42'. RD wire line.
- 14. RIH w/SPA packer. RU HES & pump 2600 gal of PAD acid in two settings. RD HES.
- 15. RU pump truck and pump scale squeeze with 100 bbl of 6490 chemical in 100 bbl of water. Flush w/200 bbl fresh water. RD pump truck. POOH w/SPA packer.
- 16. RIH w/ESP equipment set on 121 jts of 2-7/8" tubing. Intake set @3827'.
- 17. ND BOP/NU wellhead.
- 18. RDPU & RU. Clean location and return well to production.

RUPU 03/07/2013 RDPU 04/08/2013

## Work Plan Report for Well:NHSAU 421-23



## **Survey Viewer**