State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	TION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-07490	
DISTRICT II	.,		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			6. State Oil & Gas Lease No.	FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410	tec, NM 87410			′
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			NORTH HOBBS (G/SA) UNIT Section 31	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) 1. Type of Well:			8. Well No. 411	
Oil Well X	Gas Well Other	· · · · · · · · · · · · · · · · · · ·		
Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, 4. Well Location	NM 88240 505/397	-8200		
Unit Letter A : 330	Feet From The NORTH	330 Feet	From The EAST	Line
Section 31	Township 18-S	Range 38-E	NMPM	LEA County
Seed of	11. Elevation (Show whether DF, RKE			
	3645' GR			
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Groun				ace water
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction Man	terial	
12. Chec	k Appropriate Box to Indicate Natu	ire of Notice, Report, or C	Other Data SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT				
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN		
OTHER:	<u>=</u> 1	OTHER:		
13. Describe Proposed or Completed Op	perations (Clearly state all pertinent det	ails, and give pertinent dates	including estimated date of sta	rting any
proposed work) SEE RULE 1103.	For Multiple Completions: Attach we	ellbore diagram of proposed of	completion or recompletion.	· · · · · · · · · · · · · · · · · · ·
1. RUPU. Pull production equipme	nt.		· ·····	e meetic j
2. Run CNL/GR/CCL from PBTD to 3270'.				
 3. Perforate the following intervals; 4150-55 using 2 spf, 180 deg sp ph. (12 holes). 4. Stimulate perfs 4016-4252 w/2940 g 15% PAD acid. 				
5. Run Reda ESP equipment on 130 jts 2-7/8" tbg w/drain valve. Intake set @4083'.				
 Install QCI wellhead connection. NU wellhead. RDPU. Clean Location. 				
T. V. T. 0.1010000			ેટ્ર ઉત્ત	
Rig Up Date: 01/31/2006 Rig Down Date: 02/03/2006			<i>)</i>	<i>.</i>
-				11
I hereby certify that the information above is constructed or	true and complete to the best of my knowled	edge and belief. I further certify	that any pit or below-grade tank has	Depil will be
closed according to NMOCD guidelines	, a general permit	or an (attached) alternative	e OCD-approved	
DD + 4	(111)] plan		
SIGNATURE Koffell	Here		pletion Specialist DATE	02/06/2006
TYPE OR PRINT NAME Robert Gill	pert E-mail address:	robert_gilbert@oxy.com	TELEPHONE NO.	505/397-8206
For State Use Only		TITI E	DATE	: FCD 1
APPROVED BY CONDITIONS OF APPROVAL IF ANY		_ TITLE	. 43	LER 1 4 5006
COMPINED OF MIROTIDE AM.			NEET!	
		COLEUM	EMan	
		EIM!		
		200		