

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

| | | |
|---|--|---|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | WELL API NO. 30-025-28346 |
| 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other: ----- | | 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 2. Name of Operator Occidental Permian Ltd. | | 6. State Oil & Gas Lease No. |
| 3. Address of Operator 2611 State Hwy 214 Denver City, TX 79323 | | 7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit |
| 4. Well Location Unit Letter <u>P</u> : <u>1160</u> feet from the <u>South</u> line and <u>330</u> feet from the <u>East</u> line Section <u>4</u> Township <u>19S</u> Range <u>38E</u> NMPM Lea County | | 8. Well Number: 143 |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3610' (GL) | | 9. OGRID Number: 157984 |
| | | 10. Pool name or Wildcat Hobbs (G/SA) |

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU PU
2. POOH w/ ESP Equipment
3. Set CIBP @ 4090' (32' above top perf)
4. Cap w/ 35' of cement. Tag TOC.
5. Install TA wellhead
6. RDMO PU

C.O.A. Submit Current wellbore diagram.

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve Sneed TITLE Lift Specialist DATE 11/11/2015

Type or print name Steve Sneed E-mail address steve_sneed@oxy.com PHONE: 806-592-6312

For State Use Only

APPROVED BY: Markus Bravon TITLE Dist. Supervisor DATE 11/30/2015

Conditions of Approval (if any):

Rule 19.15.25.14

Set CIBP, RBP or Packer within 100 feet of uppermost perfs or open hole Pressure test to 500 psi for 30 minutes with a pressure drop of not greater than 10% over a 30 minute period

Condition of Approval: notify
OCD Hobbs office 24 hours
prior of running MIT Test & Chart
NOV 30 2015