Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natu	WELL	Revised July 18, 2013 API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION 5 Indi	-27250 cate Type of Lease	
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87	7505 0CD 6. State 0 3 2016 V-3524	e Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Leas Berry A	7. Lease Name or Unit Agreement Name Berry APN State8. Well Number	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. wei	INUMber	
2. Name of Operator Yates Petroleum Corporation		9. OGF 025575	RID Number	
3. Address of Operator			10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM 88210			Wildcat; Delaware/Berry; Bone Spring, North	
4. Well Location Unit Letter L : 1980 feet from the South line and 660 feet from the West line				
Section 5		nge 34E NMPM		
beenen	11. Elevation (Show whether DR,	<u>v</u>	County	
3731'GR				
12. Check	Appropriate Box to Indicate N	ature of Notice, Report of	or Other Data	
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM	CHANGE PLANS	SUBSEQUE REMEDIAL WORK COMMENCE DRILLING OF CASING/CEMENT JOB		
OTHER:		OTHER:		
	ork). SEE RULE 19.15.7.14 NMAG		tinent dates, including estimated date : Attach wellbore diagram of	
Yates Petroleum Corporation plans to p	lug and abandon this well as follows:			
 MIRU all safety equipment as needed Spot a 40 sx Class "H" cement plug Set a 7" CIBP at 8779' and cap it with Load hole with plugging mud. Spot top. WOC and tag, reset if necessary. Load hole with plugging mud. Spot Delaware top. WOC and tag, reset if ne Load hole with plugging mud. Spot Delaware top. WOC and tag, reset if ne Load hole with plugging mud. Spot base of salt. Load hole with plugging mud. Spot base of salt. Load hole with plugging mud. Spot base of salt. Load hole with plugging mud. Spot 8. Load hole with plugging mud. Spot 9. Perforate at 200' and pressure up to from surface to 200', if it pressures up so 10. Cut off wellhead and install dry hole. 	ed. NU BOP. 11,100'-11,320' on top of junked packet ith 40 sx Class "H" cement, this will plac a 80 sx Class "H" cement plug from 754 a 60 sx Class "C" cement plug from 554 ecessary. a 100 sx Class "C" cement plug from 161 a 40 sx Class "C" cement plug from 856 F + SQ = 180 sx Noc 500 psi in attempt to establish circulation spot a 35 sx Class "C" cement plug from e marker and clean location as per regula ify Cmt to Surface 211 S NOTIFY OC	te a plug over the open Bone Spr 80'-8311', this will place a plug 42'-5898', this will place a plug 450'-4016', this will place a plug 10'-1850', this will place a plug 0'-1050', this will place a plug ac 10'-1850', this will place a plug ac 10'-1650', this will place a plug ac 10'-1650', this will place a plug ac 10'-1050', this will place	across the stage tool and the Bone Spring across the casing shoe stage tool and g across Capitan Reef top, Yates top and across top of the salt. cross casing shoe. WOC and tag, reset if ot a plug inside and outside 7" casing tag, reset if necessary.	
	FLOGGING	OPERATIONS		
I hereby certify that the information	above is true and complete to the be	est of my knowledge and beli	et.	
SIGNATURE (June) fe	TITLE Regula	tory Reporting Supervisor	DATE November 1, 2016	
Type or print name <u>Tina Hu</u> For State Use Only		@yatespetroleum.com PH	HONE: $575-748-4168$	
APPROVED BY: Ualue Conditions of Approval (if any):	ITTLE CITOR	im ruge speadus DA	IE II J J - CO	



