Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
District 1 - (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	OV CONCERN TO THE OWNER OF THE OWNER OWNER OF THE OWNER		30-025-42290	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505			FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Salita Pe, INIVI 6	37303	6. State Oil & Ga	as Lease No.
SUNDRY NOT	ICES AND REPORTS ON WELL		7. Lease Name o	r Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	COSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A LICATION FOR PERMIT" (FORM C-101) FOR SUCH COMMENTS OF THE COMMENT OF THE COMME		Altbeir 10 State	
1. Type of Well: Oil Well	Gas Well Other HOBBS		8. Well Number 001 H	
2. Name of Operator Penroc Oil Corporation	JUL 1 1 2017		9. OGRID Number 17213	
3. Address of Operator			10. Pool name or	Wildcat
PO Box 2769, Hobbs, NM 88241	RE	CEIVED	Wildcat	
4. Well Location				
	230feet from theSouth			
Section 10	Township 18S 11. Elevation (Show whether DI	Range 36E	NMPM	Lea County
	3818	T, KKD, KT, GK, etc.,		
			Production of the Control of the Con	
12. Check	Appropriate Box to Indicate N	Nature of Notice,	Report or Other	Data
NOTICE OF INTENTION TO: SUBSEQUENT F				
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🛛	K [INIT TO DA A	
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OPNS.			INT TO PARMY P&A NR
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMEN	T JOB	P&A R
CLOSED-LOOP SYSTEM				T OUT IN
OTHER:		OTHER:	, se	bossed
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
	· · · · · · · · · · · · · · · · · · ·			
July 31, 2017 PLI Wall Service Unit - NILI BOD				
RU Well Service Unit – NU BOP. Check for tubing in the hole. If no tubing, bring 8300' of 2 7/8" tubing on pipe racks.				
TIH w/ open ended tubing (tally). Tag cement top @ 8225'. Spot 25 sxs Class "H" cement and pressure test to 500#.				
Circulate with gelled brine. Pull up to 6000'. Spot 25sxs Class "6" cement.				
Pull up to 4282'. Spot 25 sxs Class "C" cement. W.O.C. & tag. Pull up to 3100'. Spot 25 sxs Class "C" cement. W.O.C. & tag.				
Perforate squeeze hole @ 2089'. TIH w/ tbg & pkr squeeze 30 sxs Class "C" cement. W.O.C. & tag.				
Perf squeeze holes @ 150'. Circulate cement to surface – inside & out.				
RD equipment. Verify cmt to Surface all strings Remove wellhead Install DHM. Cut off anchors.				
Clean location per NMOCD reg	gulation.		-2101	RTO
,		NOTIFY OCD 24 BEGINNING PL	HOURS PRIO	RATIONS
		TIEY OCD 24	UGGING OF L.	
		NOTH NOTH	.00	
Spud Date:	Rig Release	BEGIN		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE CONTINUES	TITLE_	President	DAT	TE7/11/2017
Type or print nameM.Y. Merc	hant E-mail address:	_mymerch@penroco	oil.comPH	ONE: _575-492-1236
APPROVED BY: Wah Window TITLE Petroleum Engr. Specialist DATE 07/12/2017				
APPROVED BY: Wahle Conditions of Approval (if any):	Hirtslem TITLET etro	leum Engr. Sp	secialist DA	TE 07/12/2017

