Submit 1 Copy To Appropriate District State of New Me	
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	ral Resources Revised August 1, 2011 WELL API NO.
District II – (575) 748-1283 811 S. First St. Artesia, NM 88210	DIVISION
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 HOBI 220 South St. Fran	30-023-42290
1000 Rio Brazos Rd., Aztec, NM 87410	5. Indicate Type of Lease
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	SUS STATE X FEE
87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO	
PROPOSALS.)	Altoen 10 State
1. Type of Well: Oil Well X Gas Well Other	8. Well Number 1H
2. Name of Operator Penroc Oil Corporation	9. OGRID Number 17213
3. Address of Operator	10. Pool name or Wildcat
PO Box 2769, Hobbs, NM 88241	Wildcat
4. Well Location	
Unit Letter N : 230 feet from the South line and 1980 feet from the West line	
	Range 36E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3818'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
PULL OR ALTER CASING P&A NR PM	
PULL OR ALTER CASING PCA NR CASING/CEMENT JOB DOWNHOLE COMMINGLE P&A R	
OTHER:	OTHER:
13. Describe proposed or completed operations. (Clearly state all j	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. SEE ATTACHED SEE ATTACHED SEE ATTACHED Approved for Plugging of Wellbore for Subsequents Approved for the pugging of the contacted for and the pugging of the contacted for plugging is the contacted for plugging is the contacted for and the pugging of the pugging is the contacted for plugging is the contacted for	
proposed completion or recompletion.	
ubore origination equent	
of Weing rest subs - 2018	
plugging pendecific of cited for	
SEE ATTACHED ued for Fitetainee of Spee By contacted	
Approv bond of the ugging. build be	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion. SEE ATTACHED Approved for Plugging of wellbore greater at the completion of the completion of the completion of the completion of the completion plan. completion of the completion plan. completion of Land Office station plan.	
Thereby certify that the information above is true and complete to the best of my know approved for site restoration plan.	
NIM Stale of silv	
I hereby certify that the information above is true and complete to the best of my know approverief.	
SIGNATURE BERTELLE Pordet DATE 8/3/17	
Type or print name M. J. Merchaemail address: mymerch@pennecoPHONE: 575)492-1236	
For State Use Only	
APPROVED BY Malutation TITLE P.E.S. DATE 08/08/2017	
APPROVED BY: TITLE Conditions of Approval (if any): DATE	

Plugging Report Altbeir 10 State # 1H API 30-025-42290

7/31/2017 Furnish cement pump and operator to circulated MLF and tested casing. Casing good to 500#. Spotted 25 sx Class H cement at 8223'. POOH to 6001' and spotted 25 sx Class C cement. POOH to 4286' and spotted 25 sx Class C cement with CaCl. WOC 3 hrs and tagged at 4033'. POOH to 3111' and spotted 25 sx Class C cement. POOH and SION. Will tag in the morning.

8/1/2017 Tagged cement at 2931'. POOH and perforated 5 ½" casing at 2089'. Set packer at 1714' and squeezed perfs with 30 sx Class C cement. WOC and tagged at 1951'. Laid down remaining tubing and perforated 5 ½" casing at 150'. Established circulation and pumped cement down 5 ½" casing to perfs at 150' and up annulus to surface. Took 55 sx Class C cement to get good cement to surface. Will cut off wellhead in the morning.

8/2/2017. Dug out cellar and jack-hammered cement from around the surface head to expose the 13 3/8" casing. Cut off wellhead. Hard cement was to the surface in all three strings of casing. Installed marker and cut off anchors. Filled in cellar and moved equipment off location.