

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
HOBBS OCD
OIL CONSERVATION DIVISION
220 South St. Francis Dr.
Santa Fe, NM 87505
AUG 21 2017

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-07425
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other: TA Injector <input checked="" type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Occidental Permian Ltd.		6. State Oil & Gas Lease No.
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323		7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit Section 28
4. Well Location Unit Letter <u>C</u> : <u>990</u> feet from the <u>North</u> line and <u>2310</u> feet from the <u>West</u> line Section <u>28</u> Township <u>18S</u> Range <u>38E</u> NMPM Lea County		8. Well Number: 211
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3649' GL		9. OGRID Number: 157984
		10. Pool name or Wildcat Hobbs (G/SA)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Return to Water Injection from TA ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU Pulling Unit to return TA injector to service.
2. RIH with bit to CIBP @ 3961' and drillout.
3. Continue into open hole with bit to TD @ 4262'.
4. Deepen well open hole to new TD 4500' (Base of Unit)
5. Acid treat open hole.
6. RIH with injection equipment.
7. Perform MIT
8. RDMO PU
9. Turn well to active status for water injection.
- 10.

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17

**Condition of Approval: notify
OCD Hobbs office 24 hours
prior of running MIT Test & Chart**

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rick Reeves TITLE Production Engineer DATE 8/17/17

Type or print name Rick Reeves E-mail address rick_reeves@oxy.com PHONE: 713-215-7653

For State Use Only

APPROVED BY: Mary Brown TITLE AO/IT DATE 8/21/2017

Conditions of Approval (if any):

MB