Submit I Copy To Appropriate District Office State of New Mexico	Form C-103
Office District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88440BBS Energy Minerals and Natural R	esources Revised July 18, 2013 WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210	/ISION 30-025-28787
District III - (505) 334-6178 JAN 1 / 2010220 South St. Francis	Dr. 5. Indicate Type of Lease STATE X FEE
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM RECELL Santa Fe, NM 87505	6. State Oil & Gas Lease No. E-3633
87505  SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BA	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SU PROPOSALS.)	Anderson Ranch 10 State
1. Type of Well: Oil Well X Gas Well  Other	8. Well Number 001
2. Name of Operator	9. OGRID Number
Grand Banks Energy Co 3. Address of Operator	155471 10. Pool name or Wildcat
10 Desta Drive, Suite 300E, Midland, TX 79705	Anderson Ranch Wolfcamp
4. Well Location	
Unit Letter A : 660 feet from the North line and 660 feet from the East line	
	ge 32E NMPM Lea County
11. Elevation (Show whether DR, RKI	B, RT, GR, etc.)
4317.2 GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ RE	MEDIAL WORK ☐ ALTERING CASING ☐
	MMENCE DRILLING OPNS. P AND A
	SING/CEMENT JOB
DOWNHOLE COMMINGLE  CLOSED-LOOP SYSTEM	
	HER:
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Perfs will be added in the Wolfcamp @ 8930-8960' (8 holes and acidized w/4000 gal 15% HCL) using the following procedure. We plan to move on location	
01/22/2018.  1.MIRU WSU  2. POOH w/rods and pump R&R pump	
2 NIDWITNIIDOD	
5. NDWH NOBOP 4. Release TAC POOH w/tbg 5. MIRU Wireline Run GR-CCL PBTD (10000' +/-) to 8800'	
6. Perf 8930, 8953, 8960 w/ 2JSPF RD Wireline 7. PU RBP w/ball catcher and PKR for 5 ½ 17# csg. Hydrotest in hole 6000 psi to 9000'. Set RBP and test 1000 psi.	
8. MIRU Acid crew w/4000 gal 15% HCL	
9. Pull pkr to 8960' Spot 500 gal 15% HCL Displace 50 BW 10. Pull pkr to 8800' reverse 5 bbls and set pkr	
11. Breakdown perfs 12. Acidize with remaining 3500 gal @ 5000 psi, pump 15 bbls then (2) 7/8 BS (1.5 SG) every 10 bbls to 20 BS. Displace 55 bbls produced water. Surge as necessary	
to vac truck.  13. Wait 4 hrs  14. Swab for results	
15. Release pkr and plug. POOH	
16. TIH w the as before 17. ND BOP NUWH  DENIED	listed encumber Abo
18. Run pump and rods as before.	ns listed encumber Abo nit C101 to Add Zone, C102 rre Plan. Secure DHC permit if
Spud Date: formation. Sub-	nit C101 to Add Zone, C102 nit C101 to Add Zone, C102 ire Plan. Secure DHC permit if
and Gas out applicable	
арриос	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE Denies Jones TITLE Regulatory A	nalyst DATE 1-17-18
Type or print name Denise Jones E-mail address: Jones @	cambricament, PHONE: 432 620-9181
APPROVED BY:TITLE Conditions of Approval (if any):	DATE