

Submit 1 Copy To Appropriate District Office  
 District I - (575) 393-6161  
 1625 N. French Dr., Hobbs, NM 88240  
 District II - (575) 748-1283  
 811 S. First St., Artesia, NM 88210  
 District III - (505) 334-6178  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV - (505) 476-3460  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised July 18, 2013

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-025-26806</b>
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> <b>HOBBS OCD</b>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>RMR Operating, LLC</b>		6. State Oil & Gas Lease No.
3. Address of Operator <b>14282 Gillis Rd, Farmers Branch, TX 75244</b>		7. Lease Name or Unit Agreement Name <b>Maralo 16 State</b>
4. Well Location Unit Letter <b>M</b> : <b>660</b> feet from the <b>South</b> line and <b>760</b> feet from the <b>West</b> line Section <b>16</b> Township <b>26-S</b> Range <b>36-E</b> NMPM County <b>Lea</b>		8. Well Number <b>6Y</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>2938' GL</b>		9. OGRID Number <b>281085</b>
<b>RECEIVED</b>		10. Pool name or Wildcat <b>Sioux, Tansill-Yates-Seven Rivers</b>

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO</b> PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> CLOSED-LOOP SYSTEM <input type="checkbox"/> OTHER: _____		<b>INT TO PA</b> <b>P&amp;A NR <u>Pm</u></b> <b>P&amp;A R _____</b>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input checked="" type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>
--	--	---	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.  
 Restoration Due By **6-26-2019**

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Alan W Barksdale TITLE President DATE 8/17/18

Type or print name Alan W Barksdale E-mail address: alan@redmountainresources.com PHONE: 501-412-4097  
**For State Use Only**

APPROVED BY: Kenny Fortner TITLE Compliance Officer A DATE 8-22-18  
 Conditions of Approval (if any):

## MARALO 16 STATE #6Y (LEA COUNTY, NEW MEXICO)

06/22/18	<p>RODE EQUIP TO LOC – HELD TAILGATE SAFETY MEETING &amp; JSA. SPOTTED RIG MAT &amp; RIG. @ 2:00 PM RU. OPEN WELL – NO PRESS. DUG OUT CELLAR &amp; OPENED SURF VALVE – CHANGED IT OUT. MOVED PUMPING UNIT BACK TO HAVE ROOM TO RU WORK FLOOR. LOADED OUT 115 JTS 2-3/8" TBG FROM MARALO #2 &amp; 116 JTS 2-3/8" TBG + 146 RODS FROM MARALO #9. @ 6:00 PM CWI. SDFN.</p>
06/23/18	<p>ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING &amp; JSA. H2S, NU BOP &amp; COMMUNICATION. @ 7:00 AM OPEN WELL – NO PRESS. POOH W/ (146) 3/4" RODS. @ 11:00 AM ND WH &amp; NU BOP. RU WORK FLOOR. BEGAN TO POOH W/ TBG &amp; PULELD 14 JTS. LOST WEIGHT &amp; CON'T TO POOH W/ TOTAL OF 31 JTS (TBG PARTED – HAD SPLIT COLLAR). @ 12:30 PM SPOKE W/ GARY MCDANIEL – INFORMED HIM THAT WE WOULD NEED WORKSTRING &amp; FISHING TOOLS. HE SPOKE W/ SHEILA &amp; ADVISED ME TO SD UNTIL MONDAY MORNING TO GET WORKSTRING ON LOC. TIH W/ 30 JTS TBG, POOH &amp; LD. @ 3:00 PM CWI. SDFN.</p>
06/25/18	<p>ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING &amp; JSA ON H2S &amp; FISHING. @ 9:00 OPEN WELL – NO PRESS. WAITED ON WORKSTRING – ARRIVED ON LOC @ 11:00 AM. UNLOADED 102 JTS 2-3/8" WORKSTRING. @ 12:00 PM PU OVERSHOT, RIH W/ 1 SHOT &amp; OVERSHOT. STACKED OUT @ 30' – WORKED OVERSHOT TO NO AVAIL. LD OVERSHOT. RIH W/ TBG OPEN ENDED W/ COLLAR ON BOTTOM. TRIED TO SCREW BACK ON TBG – GOT AHOLD OF TBG. BEGAN TOOH W/ TBG – STOOD BACK 34 JTS WORKSTRING &amp; BEGAN TO LD BAD TBG. @ 1:45 PM SPOKE W/ JEFF W/ RWS – INSTRUCTED US TO RIH W/ BIT &amp; SCRAPER SO WE COULD RUN CIBP. WENT &amp; PU BIT &amp; SCRAPER FROM CAVALOS FISHING TOOLS. @ 4:30 PM PU 4-3/4" BIT &amp; SCRAPER &amp; PU WORKSTRING. RIH TO 3,200'. @ 4:55 PM SPOKE W/ KERRY W/ OCD – INSTRUCTED US TO SPOT A 50 SXS CMT PLUG ON TOP OF CIBP TO COVER PLUG @ 2,950' &amp; BRING TOC TO 2,740' &amp; MOVE ON TO PLUG @ 1,500'. @ 6:15 PM LD BIT &amp; SCRAPER. PU CIBP &amp; RIH TO 3,177'. CWI. SDFN.</p>
06/26/18	<p>ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING &amp; JSA ON H2S &amp; PERF &amp; SQZ. @ 7:00 AM OPEN WELL – NO PRESS. SET CIBP @ 3,177'. MUD UP HOLE &amp; PRESS TESTED CSG TO 500# PSI. SPOKE W/ KERRY W/ OCD – GAVE UPDATE &amp; SCHEDULED PLUGS. SPOTTED 50 SXS CMT ON TOP OF CIBP @ 3,177'. STOOD BACK 1,500' TBG IN DERRICK &amp; LD BALANCE. RIH &amp; PERF @ 1,500'. PU PKR, RIH TO 1,200' &amp; PUMPED INTO PERFS. BROKE CIRC OUT SURF CSG. SQZ 75 SXS CMT W/ 2% CACL2. POOH &amp; WOC. POOH &amp; LD PKR. RIH &amp; TAGGED TOC @ 1,387'. LD TBG. RIH &amp; PERF @ 200'. RD WORK FLOOR, ND BOP &amp; NU WH. SQZ PLUG FROM 200' TO SURF OUT 8-5/8" &amp; 5-1/2" W/ 80 SXS CMT. @ 6:00 PM CWI. SDFN.</p>

## MARALO 16 STATE #6Y (LEA COUNTY, NEW MEXICO)

06/27/18	ARRIVED ON LOC – HELD TAILGATE SAFETY MEETING & JSA ON H2S, RD, CUTTING OFF WH & WELDING DRY HOLE MARKER. @ 7:00 AM OPEN WELL – NO PRESS. DUG OUT CELLAR & CUT OFF WH. WELDED PLATE & DRY HOLE MARKER & REMOVED ANCHORS. CLEANED LOC. JOB COMPLETE.
----------	---