Submit I Copy To Appropriate District State of New Mexico	Form C-103		
Office District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011		
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.		
District II - (575) 748-1283	30-015-05598		
511 5. This 5t., Allesia, NM 88210			
District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	5. Indicate Type of Lease FEDERAL STATE FEE		
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	North Shugart Queen Unit		
1. Type of Well: Oil Well X Gas Well Other	8. Well Number 006		
Variable V			
State of New Mexico formerly Tom R. Cone	188152		
3. Address of Operator	10. Pool name or Wildcat		
1625 N. French Drive Hobbs, NM 88240	Shugart; Yates-7RVS-QU-GB		
4. Well Location			
Unit Letter K : 2310 feet from the South line and 1650 feet from the West line			
Section 21 Township 18S Range 31E	NMPM Eddy County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF		
OTHER: OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE BULE 10.15.7.14 NMAC. For Multiple Completions. Attack wellberg diagram of			

of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion.

SEE ATTACHED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	TITLE	_DATE
Type or print name	E-mail address:	PHONE:
APPROVED BY: Mahuhitah	TITLE P.E.S.	DATE 01/02/2019
Conditions of Approval (if any):		

Plugging Report NSQU #6 API 30-015-05598

12/11/2018 Moved the pumping unit back and away from the wellhead and installed BOP. Lay down 107 joints 2 3/8" tubing. Moved in workstring. Attempted gauge ring run. Could not get past 88'. Picked up bit and scrapper. Worked tight spots from 80' to 150' and from 1850' to 1950'. RIH to 3185' and POOH. Set 4 ½" CIBP at 3158'. There was a collar at 2154'. RIH with tubing. Started circulating the hole and fluid started coming up in the cellar from the surface pipe. Move vac truck into place to catch fluid and SION.

12/12/2018 Circulated MLF and spotted 25 sx cement on top of CIBP. POOH and pick up packer. Set packer at 260'. Tested casing to 600#. Casing good. Perforated casing at 2272'. Water started flowing after perforating. Set packer at 1885' and squeezed perfs with 45 sx. WOC 4.5 hrs. Opened tubing and pressure bled off immediately. Released packer and tagged cement at 2083'. POOH and perforated casing at 795'. Set packer at 260'. Pressured up to 500# with 7 bbls. Bled down to pit. Showed a small flow. Squeezed perfs with 50 sx cement. Started getting communication to the cellar while displacing. Displaced to 645'. Shut in. Very small flow coming into the cellar. Released packer and reset at 390'. Flow slowed down and stopped. Observed for 1 hour. Everything remained static.

12/14/2018 Released packer and POOH. RIH with tubing and tag at 632'. Circulated cement tot surface inside 4 ½" casing with 45 sx. Rigged down and cut off wellhead. 1" annulus to surface from 100' with 20 sx cement. Installed marker, cut off anchors, cleaned the pit and cleared location.