Submit 1 Copy To Appropriate District State of New Mexico Form C-103 Office Revised August 1, 2011 Energy, Minerals and Natural Resources District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283 30-025-07546 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 1220 South St. Francis Dr. STATE 🖂 FEE \square 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 19552 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A North Hobbs (G/SA) Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number: 331 1. Type of Well: Oil Well Gas Well Other: Injector 2. Name of Operator 9. OGRID Number: Occidental Permian Ltd. 157984 3. Address of Operator 10. Pool name or Wildcat P.O. Box 4294, Houston, TX, 77210 Hobbs (G/SA) 4. Well Location Unit Letter__ J: 1920 feet from the line and 1780 feet from the South line Section 33 **Township** 18S Range 38E **NMPM** Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3644' (GL) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABAND REMEDIAL WORK ALTERING CASING Ш **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS.□ P AND A MULTIPLE COMPL **CASING/CEMENT JOB PULL OR ALTER CASING** DOWNHOLE COMMINGLE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. HOBBS OCD
JANO 7 2019
RECEIVED During this procedure we plan to use MIRU PU, RIH with open ended tbg, Tag capped CIBP @ 3793'. the closed-loop system with a steel Spot 25 sx of cement tank and haul contents to the required WOC & TAG 3700' or Better disposal per ODC Rule 19.15.17 4. Circulate 12# Plugged mud, Pressure test casing to 500 psi 5. Perf and Sqz 100 sx of cmt at 2800' 6. WOC and Tag (Yates / Csg Shoe plug) Perf and Sqz 100 sx of cmt from 1600' WOC and Tag (Rustler plug) Perf and sqz 200 sx of cmt at 300' (58' below Surface csg shoe) and circulate to surface. Top-off as necessary (Csg Shoe plug / Surface plug) Cut off wellhead and install dry hole marker (verify cement to surface all string) with labeling 4" dia 4' Tall above ground 10. Clean up location, remove anchors Rig Release Date: Spud Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE Production Engineer SIGNATURE E-mail address carlos restrepo@oxy.com PHONE: 713-838-5772 Type or print name Carlos Restrepo For State Use Only TITLE Compliance Officer A DATE 1-11-18 APPROVED BY: Kenny Conditions of Approval (if any)

15-1/2" 70# @ 232' cmt'd w/ 425 sxs TOC @ Surf (Circ.)

9-5/8" 40# @ 2757' cmt'd w/600 sxs TOC @ 1009' (Calc.)

4.5" 12.6# @ 3871'-Surface' cmt'd w/450 sxs TOC @ surface (Circ.)

Spot 35' on top of CIBP @ 3793'

Plugged Back: 4047'-4209'

5" 18# @ 3871-4232' cmt'd w/ 50 sxs TOC @ 3871' (TOL)

7" 24# @ 3930' cmt'd w/325 sxs TOC @ 2500' (CBL)

PBTD @ 3758' TD @ 4232'

TOC @ 3871' (TOL)

PBTD @ 3758' TD @ 4232'

GENERAL CONDITIONS OF APPROVAL:

- 1) Insure all bradenheads have been exposed, identified, and valves are operational prior to rigging up on well.
- 2) Contact the appropriate NMOCD District Office no later than 24 hours prior to moving in and rigging up.
- 3) A copy of the approved C103 intent to P&A should be distributed to the onsite company and plugging representatives. Approved procedures are good for a period of one year from approved date, unless otherwise specified on the C103 intent. Approvals past this date will require the submission and approval of a new C103 intent.
- 4) A company representative is required to be present to witness all operations including setting CIBP's, circulation of mud laden fluids, perforating, squeezing or spotting cement plugs, tags, or any other operations approved on the C103 intent to P&A. Company representative should contact the NMOCD and report all operations.
- 5) Any changes that may be required during plugging operations should be approved by the NMOCD before proceeding.
- 6) A closed loop system is to be used for all plugging operations. Contents of the steel pits to be hauled to a NMOCD permitted disposal facility.
- 7) Mud laden fluids must be placed between all cement plugs mixed at 25 sacks of salt gel per 100 barrels of brine.
- 8) All cement plugs will be 100' or 25 sacks cement, whichever is greater. Class 'C' cement will be used above 7500' and Class 'H' below 7500'. Plugs should be no more than 3000' apart
- 9) Site remediation due within one year of well plugging completion.