Submit 1 Copy To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources Revised July 18, 2013 District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 OIL CONSERVATION BESISSEN District II - (575) 748-1283 30-025-33398 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. Santa Fe, NM/W/5050 2019 District III - (505) 334-6178 STATE 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM NM-86923 87505 SUNDRY NOTICES AND REPORTS ON WEREC 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Bitsv Federal SWD DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1 1. Type of Well: Oil Well Gas Well X Other SWD 9. OGRID Number 2. Name of Operator Foundation Energy Management, LLC 10. Pool name or Wildcat 3. Address of Operator 5057 Keller Springs Rd, Suite 650, Addison, Texas 75001 Delaware 4. Well Location Unit Letter : 1980 660 feet from the East feet from the North line and line Section Township 23 South **NMPM** Range 32 East County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,550' GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. P AND A **PULL OR ALTER CASING** MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE **CLOSED-LOOP SYSTEM OTHER: Add Delaware Injection Perfs** X OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. NMOCD Order No. SWD-1156 dated 12/12/2008 authorized Enervest Operating, LLC (now Foundation Energy Management, LLC) to utilize the Bitsy Federal SWD No. 1 as a produced water disposal well. Injection can occur into the Delaware formation from 4660-6270 feet. This well is currently completed as a produced water disposal well through perforations from 5301-5637, and 6166-6206 ft. In order to increase injectivity and reduce the injection pressure, Foundation Energy Management, LLC proposes to add injection perforations in the Delaware formation from 4990 to 5020, 5040 to 5070, and 5080 to 5110 feet. The exact location of the additional perforations, which is not known as this time will be determined by log analysis. However, all additional perforations will be in compliance with Oder No. SWD-1156, and will be reported in a subsequent Upon completion of perforating and acidizing, plastic-coated injection tubing will be set in a packer located within 100 ft of the uppermost injection perforations. Attached is a specific procedure describing the proposed operations. 6/17/2019 Rig Release Date: 6/19/2019 I hereby certify that the information above is true and complete to the best of my knowledge and belief. **SIGNATURE** Type or print name For State Use Only

TITLE

APPROVED BY:

Bitsy Federal #1 SWD

Sand Dunes
Add Perfs to Increase Injection Capacity and Lower Pressure
Lea, County NM

Casing /Tubular Details and Capacities:


TUBULAR	SIZE	GRADE	DEPTH (ft)	WEIGHT (ppf)	CEMENT (sx)	TOC (ft)	
Surface Casing	13-3/8"	H-40	858	48	650	SFC	Circ
Intermediate Casing	8-5/8"	J-55	4338	32	1500	SFC	Circ
Production Casing	5-1/2"	K-55	9442	17	1330	SFC	Circ
Producing Tubing	2- 7/8"	IPC	4900	6.4	n/a	n/a	n/a

Procedure:

- 1. MIRU WO Rig
- 2. Kill well if necessary, using 2% KCL.
- 3. ND WH. NU BOP
- 4. Unseat Packer, PU joints and lower tubing to tag for fill.
- 5. TOOH with TBG. Tally as POOH and note tagged depth.
- 6. If fill is covering existing perfs, cleanout to TD before proceeding to next step.
- 7. MIRU wireline
- 8. RIH with 3 1/8" gun and perf new injection perfs from 4490-5020, 5040-5070, and 5080-5110.
- 9. POOH with WL guns
- 10. RD Wireline
- 11. PU and RIH with redressed packer and RIH with tubing.
- 12. Hydrotest as RIH to 6000 psi.
- 13. Set packer above new perfs at +/- 4910'
- 14. MIRU acid crew and test flowlines
- 15. Pump acid job according to pump schedule. 5,000-10,000 gals 7.5% NEFE HCl w/ scale inhibitor, clay stabilizer and ball sealers.
- 16. RDMO acid crew.
- 17. Pressure test packer is holding to 500 psi and 1000 psi for 10 min each.
- 18. Perform injection test to determine injection rate and pressure.
- 19. RDMO Wo Rig.
- 20. Reconnect equipment for disposal.

Bitsy Federal 1

Current WBD



Bitsy Federal 1 Proposed WBD

