

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-21231
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator SPICEWOOD SOUTHWEST OPERATING COMPANY, LLC		6. State Oil & Gas Lease No.
3. Address of Operator 20308 HWY 71 WEST SUITE 6 SPICEWOOD, TX 78669		7. Lease Name or Unit Agreement Name STATE A
4. Well Location Unit Letter C : 752 feet from the NORTH line and 2092 feet from the WEST line Section 05 Township 24S Range 38E NMPM County LEA		8. Well Number 2
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3293' GR		9. OGRID Number 329108
		10. Pool name or Wildcat STATELINE: ELLENBURGER

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: RETURN TO PRODUCTION ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

09-20-19: RIG UP SLICKLINE. GIH W/ GAUGE RING & TAG SOFT FILL @ 10,040'. FLUID FOUND @ 700'. RD SLICKLINE.

09-27-19: TP: 0PSI. UNLOAD FRAC TK. HOOK UP LINE FROM WH TO TANK. SWAB WELL 450'-1770', 17RUNS. 37BF (20% OIL CUT). SWI.

10-01-19: TP: 5PSI. BLOW WELL DOWN. SWAB WELL 640'-2040', 16RUNS, 46BF (ALL WATER). SWI.

10-08-19: TP: 5PSI. BLOW WELL DOWN. SWAB WELL 150'-1000', 10RUNS, 50BF (ALL WATER). SWI.

10-19-19: TP: 25PSI. BLOW WELL DOWN. SWAB WELL 450'-2000', 8RUNS. 59BF (ALL WATER). SWI.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wyatt Lautzenheiser TITLE OPERATIONS MANAGER DATE 10-25-19

Type or print name WYATT LAUTZENHEISER E-mail address: WYATT@SPICEWOODOPERATING.COM PHONE: 512-610-0552

For State Use Only

APPROVED BY: [Signature] TITLE Petroleum Engineer DATE 11/05/19
Conditions of Approval (if any):