

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-41550

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
North Hobbs (G/SA) Unit

8. Well Number: 946

9. OGRID Number: 157984

10. Pool name or Wildcat
Hobbs (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other: -----

2. Name of Operator
Occidental Permian Ltd.

3. Address of Operator
P.O. Box 4294, Houston, 77210-4294

4. Well Location

Unit Letter O : 1104 feet from the S line and 1670 feet from the E Line
Section 18 Township 18-S Range 38-E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3676' (KB)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU Pulling Unit and reverse unit.
2. RIH with CICR set @ ~ 4200
3. Cement sqz existing perfs
4. RIH with 6-1/8" bit and DO CICR and Cement to ~ 4400' (New PBTD)
5. RU WL and perf as following: 4158 - 4168, 4180 - 4188, 4196 - 4206, 4216 - 4224, 4232 - 4240, 4266 - 4276, 4284 - 4292, 4304 - 4314, 4324 - 4334, 4342 - 4352, 4360 - 4368, 4376 - 4384. RD WL
6. RIH with PPI tool acid treat new pwerfs with 5400 gal HCL 15%. POOH with PPI tool
7. RIH with ESP equipment
8. Place well back in service

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Production Engineer

DATE 1/24/2020

Type or print name

Carlos Restrepo

E-mail address carlos_restrepo@oxy.com

PHONE: 713-366-5147

For State Use Only

Petroleum Engineer

APPROVED BY:

TITLE

DATE

01/30/2020

Conditions of Approval (if any):

Additional Data that would not fit on the form.