RECETALIA	
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office District I Energy, Minerals and Natural Resources	Revised March 25, 1999 WELL API NO.
District I 1625 N. French Dr., Hobbs, NN 18240 4 2008 Energy, Minerals and Natural Resources OF Property Construction OF Property Services and Natural Resources OF Property Construction OF Propert	30-025-31318
District III B 82.10 TO LE 20 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE □
1000 Rio Brazos Rd., Aztec, NM 8741 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St Francis Dr., Santa Fe, NM 87505	V-2199
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name:
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other	Gem,87.05 JV-P
2. Name of Operator	8. Well No.
BTA Oil Producers 003002 OCD-ARTESIA	6
3. Address of Operator 104 S. Pecos, Midland, TX 79701	9. Pool name or Wildcat Gem (Morrow) East
4. Well Location	com (menon) 2000
TY Y Y 1000 fort from the Court line and	1980 feet from the West line
Unit Letter K : 1980 feet from the South line and	1980 leet from the <u>west</u> line
Section 2 Township 20S Range 33E NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, 6 3579' GL 3593' KB	etc.)
11. Check Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WO	BSEQUENT REPORT OF:
TEMPORARILY ABANDON TO CHANGE PLANS COMMENCE D	RILLING OPNS. PLUG AND
PULL OR ALTER CASING MULTIPLE CASING TEST COMPLETION CEMENT JOB	ABANDONMENT AND
Office and a second sec	rf / Test well / TA
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagrant of proposed completion or recompilation.	
BTA Oil Producers tested this well as follows:	FEB - 4 20°)
1/15/08 MI & RU PU. ND WH. NU BOP. Attempt to rel pkr. 1/16/08 Unseat pkr. POH w/tbg & pkr. RU WL. RIH w/RBP. Set RBP @ 130 1/17-22/08. Circ. POH w/tbg. Test tbg in hole. RIH w/tbg & pkr. Set pkr @1262 Perf 12710-716' w/2 JSPF. Swab. Making water, no gas or oil. 1/23/08 POH w/tbg & pkr. Set CIBP @ 12765'. Dmp 40' cmt on top. Press ts 1/24-25/08 RIH w/tbg, POH w/tbg. ND BOP. NU WH flange w/needle valve and	t csg & plug to 500 psi – OK. (Chart attached.)
Well TA'd. This Approval of Abandonment Ex	Femporary 128/2013
SIGNATURE AMOUNT TITLE Regulatory Admi	inistrator DATE 01/29/08
Type or print name Pam Inskeep pinskeep@btaoil.com	Telephone No. 432-682-3753
(This space for State use)	AND O O OAN
APPPROVED BY TITLE Geologist Conditions of approval, if any:	date <u>MAR 2 8 2</u> 008

