Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR


FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010


101	UREAU OF LAND MANAGE	CONTRACTOR OF THE PARTY OF THE	Expire	28: July 31, 2010	
	5. Lease Serial No. NMNM09015				
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allotte	e or Tribe Name	
SUBMIT IN TRI		7. If Unit or CA/Agreement, Name and/or No. MALJAMAR GRAYBURG			
1. Type of Well	8. Well Name and N MALJAMAR GF	8. Well Name and No. MALJAMAR GRAYBURG 27			
☐ Oil Well ☐ Gas Well ☑ Oti  2. Name of Operator FOREST OIL CORPORATION	Contact: CI	9. API Well No. 30-025-00453	9. API Well No. 30-025-00453		
3a, Address 707 17TH STREET SUITE 36	o. Phone No. (include area cod h: 303-812-1554	e) 10. Field and Pool,	10. Field and Pool, or Exploratory MALJAMAR GRAYBURG SA		
DENVER, CO 80202  4. Location of Well (Footage, Sec., 7		000 012 100 .	11 County or Paris		
Sec 4 T17S R32E SWSE 990			LEA COUNTY COUNTY, NM		
380 4 1 170 N32E 3W0E 300		<b>33</b> ,7333,77			
12. CHECK APPI	ROPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Fracture Treat	□ Reclamation	☐ Well Integrity	
☐ Subsequent Report	Casing Repair	☐ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	□ Change Plans	Plug and Abandon	☐ Temporarily Abandon		
	☐ Convert to Injection	Plug Back	☐ Water Disposal		
following completion of the involved testing has been completed. Final Al determined that the site is ready for f  Plugging Procedure:  1 - MIRUPU. POOH w/downh  2. Fill hole w/heavy mud from  3. Fill hole w/heavy mud from  4. Fill hole w/heavy mud from ement, an leave a 100' cement	operations. If the operation results candonment Notices shall be filed of inal inspection.)  sole equipemtn as requried.  3,838 to approx 1,800'. Spot top of plug @ 1800 to 800'. top of plug @ 800' to 320'. It plug at 320'.	in a multiple completion or really after all requirements, included at a 100' cement plug  Spot a 100; cement plug  Shoot a squeeze perf	@ 500 TOS 800'	160-4 shall be filed once d, and the operator has	
14. Thereby certify that the foregoing is	Electronic Submission #625	97 verified by the BLM We CORPORATION, sent to	ell Information System the Hobbs		
Name(Printed/Typed) CINDY BUSH		Title SR RE	Title SR REGULATORY TECH		
Signature (Electronic S	Submission)	Date 08/28/	Date 08/28/2008		
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE		
Approved By	901.	Title		Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	itable title to those rights in the sub				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Additional data for EC transaction #62597 that would not fit on the form

- 32. Additional remarks, continued
- 5. Spot a cement plug @ 60' to surface.
- 6. Cut off casing, Install dry hole marker.
- 7. Remediate surface location as necessary.





MGBU #27 WBD May 08.xls