

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised March 25, 1999

**DISTRICT I**  
1625 N. French Dr., Hobbs, NM 88240  
**DISTRICT II**  
811 South First, Artesia NM 88210  
**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
**DISTRICT IV**  
2040 South Pacheco, Sante Fe, NM 87505

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
**30-025-10133**

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

**Exxon Mobil Corporation**

3. Address of Operator **P.O. Box 4358**

**Houston**

**TX 77210-4358**

8. Well No.

**12**

9. Pool name or Wildcat

**Blinebry Oil and Gas (Oil) Wantz/ABO**

4. Well Location

Unit Letter **O** : **660** Feet From The **south** Line and **1880** Feet From The **east** Line

Section **9** Township **22S** Range **37E** NMPH Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
**3426 KB**

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: **Add Wantz; ABO perforations** ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion)

**05/13/2001 - Sqz Blinebry perfs (5380' - 5776') w/ nitrogen & cement ( 43,000 SCF N2).**

**05/14/2001 - Tagged cmt @ 5270'. D/O cmt to 5800'. C/O to CIBP @ 6077'. D/O CIBP @ 6077' and C/O to 7200'.**

**05/15/2001 - Ran logs: GR/Caliper/Temp log. Added Wantz/ABO perfs (6750' - 59'; 6818' - 37'; 6875' - 84') w/ 3-3/8" gun, 2 SPF, 90° phasing.**

**05/17/2001 - Water frac Wantz/ABO perfs w/ 93,000 gals Econoprop & flush w/ 2500 gals linear gel.**

**06/18/2001 - RIH w/ ret. bridge plug and pkr. Set RBP @ 5805' and pkr @ 5800'. Test plug to 800 PSI, OK. Rls pkr & circ well w/ 2% KCL water.**

**06/19/2001 - Spot acid across Blinebry perfs (5380' - 5776'). Pulled pkr up to 5278' and pumped rock salt acid job. Pulled pkr. Tagged salt @ 5800'.**

**06/20/2001 - Washed salt down to 5805'. Latch onto and release RBP. POOH. RIH w/ 2-3/8" production tbg. RWTP.**

**DHC Order No. 0028**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Jamie A. Robinson* TITLE **Staff Office Assistant**

TYPE OR PRINT NAME **Jamie A. Robinson**

TELEPHONE NO. **(281) 654-1948**

(This space for State Use)

APPROVED BY *[Signature]* TITLE **PETROLEUM ENGINEER**

CONDITIONS OF APPROVAL IF ANY:

DATE **DEC 12 2003**