State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

	OIL CONSERV	ATION DIVISION		
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 BBS O	CD 1220 South Santa Fe,	St. Francis Dr. NM 87505	WELL API NO. 30-025-37445	
DISTRICT II			5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM ARR 27	2011		STATE ·	FEE X
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410			6. State Oil & Gas Lease No.	
SUNDR PROTECTION	AND REPORTS ON WE	LLS	7. Lease Name or Unit Agreem	nent Name
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLI			North Hobbs (G/SA) Section 19	
Type of Well: Oil Well X	Gas Well Other		8. Well No. 733	
Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator HCR 1 Box 90 Denver City, TX 793	22		10. Pool name or Wildcat	Hobbs (G/SA)
4. Well Location	23			
Unit Letter I : 1690 I	Feet From The South	1080 Fee	t From The East	Line
Section 19	Township 18-S	Range 38E	NMPM	Lea County
	1. Elevation (Show whether DF, RI 3655' GL	KB, RT GR, etc.)		
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Bel	low-Grade Tank: Volume	bbls; Construction Ma	terial	
12. Check Ap NOTICE OF INTENT	propriate Box to Indicate Na			
			SEQUENT REPORT OF	
	UG AND ABANDON	REMEDIAL WORK	ALTERING	
TEMPORARIET ABANDON CF	HANGE PLANS	COMMENCE DRILLING OP	NS PLUG & AI	BANDONMENT []
DULL OD ALTED CACING				
	Iltiple Completion	CASING TEST AND CEMEN	T JOB	
OTHER: Clean out/OAP/ acid treat	X	OTHER:		
	ons (Clearly state all pertinent de	OTHER:etails, and give pertinent dates.	including estimated date of st	arting any
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For M. 1. Kill well.	ons (Clearly state all pertinent de	OTHER:etails, and give pertinent dates.	including estimated date of st	arting any
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For M 1. Kill well. 2. Clean out to 4500'.	ons (Clearly state all pertinent de Multiple Completions: Attach w	OTHER:etails, and give pertinent dates.	including estimated date of st	arting any
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For M 1. Kill well. 2. Clean out to 4500'. 3. Perforate hole @4435-4438, 4453-4484	ons (Clearly state all pertinent de Multiple Completions: Attach w	OTHER:etails, and give pertinent dates.	including estimated date of st	arting any
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For M 1. Kill well. 2. Clean out to 4500'. 3. Perforate hole @4435-4438, 4453-4484 4. Acid treat well w/2000 gal of 15% PAD 5, Perform scale squeeze.	ons (Clearly state all pertinent de Multiple Completions: Attach w	OTHER:etails, and give pertinent dates.	including estimated date of st	arting any
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For M 1. Kill well. 2. Clean out to 4500'. 3. Perforate hole @4435-4438, 4453-4484 4. Acid treat well w/2000 gal of 15% PAD 5, Perform scale squeeze. 6. Run back in hole w/ESP equipment.	ons (Clearly state all pertinent de Multiple Completions: Attach w	OTHER:etails, and give pertinent dates.	including estimated date of st	arting any
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For M 1. Kill well. 2. Clean out to 4500'. 3. Perforate hole @4435-4438, 4453-4484 4. Acid treat well w/2000 gal of 15% PAD 5, Perform scale squeeze.	ons (Clearly state all pertinent de Multiple Completions: Attach w	OTHER:etails, and give pertinent dates.	including estimated date of st	arting any
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For M 1. Kill well. 2. Clean out to 4500'. 3. Perforate hole @4435-4438, 4453-4484 4. Acid treat well w/2000 gal of 15% PAD 5, Perform scale squeeze. 6. Run back in hole w/ESP equipment.	ons (Clearly state all pertinent de Multiple Completions: Attach w	OTHER:etails, and give pertinent dates.	including estimated date of st	arting any
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For M 1. Kill well. 2. Clean out to 4500'. 3. Perforate hole @4435-4438, 4453-4484 4. Acid treat well w/2000 gal of 15% PAD 5, Perform scale squeeze. 6. Run back in hole w/ESP equipment.	ons (Clearly state all pertinent de Multiple Completions: Attach w	OTHER:etails, and give pertinent dates.	including estimated date of st	arting any
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For M 1. Kill well. 2. Clean out to 4500'. 3. Perforate hole @4435-4438, 4453-4484 4. Acid treat well w/2000 gal of 15% PAD 5, Perform scale squeeze. 6. Run back in hole w/ESP equipment.	ons (Clearly state all pertinent de Multiple Completions: Attach w	etails, and give pertinent dates, rellbore diagram of proposed c	including estimated date of stompletion or recompletion.	
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For Moderate Proposed work SEE RULE 1103. For M	ons (Clearly state all pertinent de Multiple Completions: Attach w	etails, and give pertinent dates, rellbore diagram of proposed c	including estimated date of stompletion or recompletion.	
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For Moderate Proposed work SEE RULE 1103. For M	ons (Clearly state all pertinent de Multiple Completions: Attach w., acid.	etails, and give pertinent dates, ellbore diagram of proposed content of the diagram of proposed of the diagram of the diag	including estimated date of stompletion or recompletion. hat any pit or below-grade tank ha	
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For Moderate Number 1. Kill well. 2. Clean out to 4500'. 3. Perforate hole @4435-4438, 4453-4484. 4. Acid treat well w/2000 gal of 15% PAD 5, Perform scale squeeze. 6. Run back in hole w/ESP equipment. 7. Return well to production. I hereby certify that the information above is true and constructed or closed according to NMOCD guidelines.	ons (Clearly state all pertinent de Multiple Completions: Attach w., ., acid.	etails, and give pertinent dates, rellbore diagram of proposed control of the degree and belief. I further certify to or an (attached) alternative plan	including estimated date of stompletion or recompletion. hat any pit or below-grade tank ha	s been/will be
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For M. 1. Kill well. 2. Clean out to 4500'. 3. Perforate hole @4435-4438, 4453-4484 4. Acid treat well w/2000 gal of 15% PAD 5, Perform scale squeeze. 6. Run back in hole w/ESP equipment. 7. Return well to production. I hereby certify that the information above is true and constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson For State Use Only	ons (Clearly state all pertinent de Multiple Completions: Attach w., ., acid.	edge and belief. I further certify t or an (attached) alternative plan TITLE Administrative amendy johnson@oxy.com	including estimated date of stompletion or recompletion. hat any pit or below-grade tank ha OCD-approved Associate TELEPHONE NO.	04/26/2011 806-592-6280 APR 2 8 2011
OTHER: Clean out/OAP/ acid treat 13. Describe Proposed or Completed Operation proposed work) SEE RULE 1103. For Moderate Notes 1. Kill well. 2. Clean out to 4500'. 3. Perforate hole @4435-4438, 4453-4484. 4. Acid treat well w/2000 gal of 15% PAD 5, Perform scale squeeze. 6. Run back in hole w/ESP equipment. 7. Return well to production. I hereby certify that the information above is true are constructed or closed according to NMOCD guidelines. SIGNATURE TYPE OR PRINT NAME Mendy A. Johnson	ons (Clearly state all pertinent de Multiple Completions: Attach w., ., acid.	edge and belief. I further certify to an (attached) alternative plan TITLE Administrative amendy johnson@oxy.com	including estimated date of stompletion or recompletion. hat any pit or below-grade tank ha OCD-approved Associate DATE TELEPHONE NO.	04/26/2011 806-592-6280 APR 2 8 2011