

COPIES RECEIVED		
CONTRIBUTION		
STATE FEE		
FEE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

AMENDED

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
E-7332

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Tipperary Oil & Gas Corporation	8. Farm or Lease Name Sinclair State
3. Address of Operator P.O. Box 3179, Midland, Texas 79702	9. Well No. 2
4. Location of Well UNIT LETTER <u>L</u> , <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>22</u> TOWNSHIP <u>11-S</u> RANGE <u>33-E</u> NMPM.	10. Field and Pool, or Wildcat North Bagley Penn
15. Elevation (Show whether DF, RT, GR, etc.)	12. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug & abandon as follows:

- Spot 100 sx plug @ 6765' (Point of casing collapse)
- Cut & pull 4 1/2" csg fr. approx. 4000'
- Spot 50 sx @ top of 4 1/2" csg.
- Spot 50 sx @ 7 5/8" csg @ 3750'
- Cut 7 5/8" csg @ 1000'
- Spot 100' plug @ top of 7 5/8" csg.
- Spot 100' plug @ 10 3/4" shoe, 367'
- Spot 10' plug @ surface w/regulation marker.
- Clean & lever location.

NOTE: Amends Original Form C-103 filed 10-6-77 to correct point of csg. collapse

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Production Manager DATE 11-18-77

APPROVED BY Jerry Sexton TITLE Dist. 1, Sup. DATE NOV 21 1977

CONDITIONS OF APPROVAL, IF ANY: