

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.  
**K-5265-1**

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Sun Oil Company</b>	8. Farm or Lease Name <b>New Mexico "M" State</b>
3. Address of Operator <b>P. O. Box 1861, Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>D</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>19</b> TOWNSHIP <b>10-S</b> RANGE <b>34-E</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>Vada Penn</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4227 RDB</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/8/76 MIRU James & Caffey  
5/11/76 POOH w/rods & tbg. Ran CIBP on WL & set @ 9830'. Dump bailed 3 sx cmt on top of CIBP to 9795.  
5/12/76 Circ hole w/9.5# mud & LD tbg.  
5/13-14/76 Ran freepoint & cut 5½" csg @ 5503'. POOH w/total of 171 jts (5566')  
5/15/76 Sptd 30 sx cmt plug 5514-5414 & 35 sx @ 4050-3950'.  
5/17/76 Ran free point & cut 8-5/8" csg @ 843'. Rec'd total of 851' (26 jts).  
5/18/76 Sptd 50 sx cmt plug 890-790 & 65 sx cmt plug 465-365'. Placed 15 sx plug @ the surface & welded on steel plate & installed permanent marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles Gray TITLE Proration Analyst DATE 5/27/76  
APPROVED BY John W. Runyon TITLE \_\_\_\_\_ DATE 5/11 1977  
CONDITIONS OF APPROVAL, IF ANY: