

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease
 State Fee
 5. State Oil & Gas Lease No.
 OG 4541

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER
 2. Name of Operator
 WESTERN STATES PRODUCING COMPANY
 3. Address of Operator
 900 Bldg. of the Southwest, Midland, Texas 79701
 4. Location of Well
 UNIT LETTER O, 660 FEET FROM THE South LINE AND 2100 FEET FROM
 THE East LINE, SECTION 4 TOWNSHIP 11-S RANGE 34-E N.M.P.M.

7. Unit Agreement Name

 8. Farm or Lease Name
 T. P. State "4"
 9. Well No.
 1
 10. Field and Pool, or Wildcat
 Inbe (Penn)

15. Elevation (Show whether DF, RT, GR, etc.)
 4220' GL
 12. County
 Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Displaced 20 sack cement plug from 7900' back to 7617' in 4 1/2" casing.
- Shot off 4 1/2" casing at 7850', shot at 6000' & 5540'. Pulled 5540' of 4 1/2" casing. Set 50 sack plug at 5410' - 5310'. Set 50 sack plug at 4110' - 4010'. Laid down 4 1/2" casing.
- Shot off 8 5/8" casing at 2510', 2000', 1554', & 1130'. Pulled 1130' of 8 5/8" casing.
- Ran tubing and spotted 50 sack cement plug from 1083' to 983'.
- Spotted 75 sack cement plug from 410' to 310'.
- Cut off well head and spotted 10 sack cement plug.
- Set marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Operations Manager DATE 8-11-71

APPROVED BY [Signature] TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 13 1917

OIL CONSERVATION COMM.
HOBBES, I. I.