

(May 1963)

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

(Other instructions reverse side)

Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 058677-A

SUNDRY NOTICES AND REPORTS

(Do not use this form for proposals to drill or to deepen or plug back to adjacent reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

JUN 20 1978

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR SNB OPERATING CO.	8. FARM OR LEASE NAME New Mexico Federal B 1A
3. ADDRESS OF OPERATOR Post Office Box 906, Lovington, New Mexico 88260	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* Use also space 17 below.) At surface 1980' FSL - 1980 FWL	10. FIELD AND POOL, OR WILDCAT South Prairie Cisco
14. PERMIT NO. Blanket	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4111
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 21-8-36
	12. COUNTY OR PARISH Roosevelt
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input checked="" type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pulled pumping equipment and perforated section from 9480 to 9486 -
Ran RBP and packer and set BP @ 9530 and packer @ 9450 -
Acidize section w/1000 MCA acid and had no show of oil or gas.

This approval of temporary abandonment expires 3-31-79

18. I hereby certify that the foregoing is true and correct

SIGNED C. D. July TITLE Production Foreman DATE 06/15/78

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
G. G. L.
JUN 21 1978
U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side