

WATER CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

50. Indicate Type of Lease
 State Fee
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG WELLS TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL GAS WELL OTHER

7. Unit Agreement Name

Name of Operator
Ike Lovelady, Inc.

8. Farm or Lease Name
Lignum

Address of Operator
P.O. Drawer 2666; Midland, Texas 79702

9. Well No.
1

Location of Well
 UNIT LETTER A 660 FEET FROM THE north LINE AND 660 FEET FROM
 THE east LINE, SECTION 35 TOWNSHIP 8-S RANGE 37-E N.M.P.M.

10. Field and Pool, or Wildcat
Wildcat

15. Elevation (Show whether DF, RT, GR, etc.)
3995.2 Gr

12. County
Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK
 TEMPORARILY ABANDON
 PULL OR ALTER CASING
 OTHER

PLUG AND ABANDON
 CHANGE PLANS

REMEDIAL WORK
 COMMENCE DRILLING OPNS.
 CASING TEST AND CEMENT JOB
 OTHER

ALTERING CASING
 PLUG AND ABANDONMENT
 Completion

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 2/18/82 MI WSU - Ran 4-3/4" bit & 2-3/8" Tbg. Drill out DV Tool @ 2128'. POH perforate 2/SPF @ 4808, 15, 21, 26, 33, 38, 58, 61, 72, 77, & 81.
- 2/19/82 RIH W/Pkr, SN, & Tbg. Set Pkr. @ 4746;. Swab 20 BLW, Tbg. dry No Shows.
- 2/20/82 Acidize W/500 Gals. 15% NE Acid @ 1600# max 1200# Min. @ 2 BPM. Swab 20 BLW & 1/2 BO Tbg. dry.
- 2/22/82 TPC 14 Hrs. 175#. FL 3600' FS. Swab 8 Hrs. recover 6 BO & 0 BW.
- 2/24/82 Acidize W/1500 Gals. 15% NEFE W/40 ball sealers. Max 2000# Min 1000# @ 3-1/2 BPM. Flow & swab 52 BLW.
- 2/26/82 Acidize W/6000 Gals 15% NEFE & 40 ball sealers. Ball out to 5200#.
- 3/1/82 TPC 200# Swab 20 BLW & 5 BO.
- 3/2/82 TPC 900# Swab 9 BLW & 18 BO.
- 3/5/82 PQH W/Tbg. & Pkr. Ran Production string, pump, & rods. MOWSU. Waiting on Pumping Unit.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Burrow TITLE Manager of Production DATE 3/8/82

ORIGINAL SIGNED BY
JERRY SEXTON

MAR 15 1982

APPROVED BY _____ TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY: