

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
LG 3716

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>RE-Entry</u>	7. Unit Agreement Name
2. Name of Operator <u>Yates Petroleum Corporation</u>	8. Farm or Lease Name <u>Midwest-Hightower ADS St.</u>
3. Address of Operator <u>207 South 4thSt., Artesia, NM 88210</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>12S</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat <u>Wildcat</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4305.4' GR</u>	12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Set CIBP, Perforate, Treat</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

2-22-86. Set CIBP at 10250' w/30' cement on top. Squeezed perms 9952-83' w/45 sx in formation to 3750#. WIH and perforated 9878-87' w/10 .50" holes. Acidized perms 9878-87' w/1000 gals 15% NEFE acid and 15 ball sealers. Flowed back. Swabbed w/no shows.

3-3-86. WIH and perforated 9516-34' w/13 .50" holes as follows: 9516, 18, 19, 20, 21, 22, 24 (7 holes); 9531-34' (6 holes - 2 SPF). Acidized perms 9516-34' w/2500 gals 15% NEFE acid and 25 ball sealers. Swabbed well.

3-10-86. WIH and perforated 9461-65' w/8 .42" holes (2 SPF). Acidized perms 9461-65' w/1500 gals 15% NEFE acid and 10 ball sealers. Swabbed with no shows.

3-12-86. WIH and perforated 9251-66' w/9 .50" holes as follows: 9251, 52, 53, 54, 62, 63, 64, 65 and 66'. Acidized perms 9351-66' w/2500 gals 15% NEFE acid and 20 ball sealers. Flowed and swabbed back with no shows.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Production Supervisor DATE 3-14-86

APPROVED BY JERRY SEXTON DISTRICT I SUPERVISOR TITLE \_\_\_\_\_ DATE MAR 17 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
MAR 17 1986  
C.C.D.  
HOBBS OFFICE