

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
L-5298

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO UNPLUG OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER- Dry

2. Name of Operator
Viking Petroleum, Inc.

3. Address of Operator
2761 E. Skelly Drive, Tulsa, Oklahoma 74105

4. Location of Well
UNIT LETTER H 1980 FEET FROM THE North LINE AND 600 FEET FROM
THE East LINE, SECTION 31 TOWNSHIP 13S RANGE 34E NMPM.

5. Elevation (Show whether DF, RT, GR, etc.)
4164.8' GR

7. Unit Agreement Name
N/A

8. Farm or Lease Name
Dome Nombre 31 State

9. Well No.
1

10. Field and Pool, or Wildcat
Wildcat

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data-

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
- Started Plugging & Abandonment Procedures 7/8/82.
 - Pulled tubing out of hole.
 - Set CIBP at 10,300'.
 - Dump 35' of cement on top of CIBP.
 - Cut and pulled 5037' of 5½" casing.
 - Set a 70 sx cement plug at 5700'.
 - Set a 50 sx cement plug at 5050' across 5½" stub.
 - Set a 50 sx cement plug at 4250' across 8-5/8" shoe.
 - Set a 50 sx cement plug at 1550' across salt section.
 - Cleaned out cellar and cut off head.
 - Set a 10 sx cement plug at surface.
 - Install a dry hole marker 7/17/82.

RECEIVED
SEP - 9 1982
OIL CONSERVATION DIVISION
SANTA FE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE [Signature] DATE _____

APPROVED BY [Signature] TITLE **OIL & GAS INSPECTOR** DATE **NOV 9 1982**

CONDITIONS OF APPROVAL, IF ANY: