

MCA No. 219

Pg 2

To 3842 f set. Acidize in 2 stages using 50 bbls
15% HCL-NE-FE followed w/ 30 BTFW. Orient w/ 500'
rocksalt in 8 bbls gelled brine. Pump 50 bbls acid.
Flush w/ 50 bbls TFW. Shut-in. Flowback. Swab-well.
Release plm & POOH. G-IH. Circ clean to 4019'. POOH.
Run producing equipment & place on production.