

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
B-9955

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Mobil Oil Corporation	8. Farm or Lease Name New Mexico C
3. Address of Operator Box 633, Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 4 TOWNSHIP 15-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Saunders Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4209 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 25 SRS*
- Run tubing (must be picked up) and spot 100' cement plug ~~(15-20)~~ over perforated interval back to 9700'. Tag plug after initial set. If plug does not set do 1-A.
1-A. Run retainer to 9700' and squeeze perforations - 30 sx - and come off the retainer.
 - Circulate hole to mud laden fluid and pull tubing.
 - Spot 10 sx cement plug at surface (25-30).
 - Clear wellhead, erect monument.

Note: No casing available for economic salvage.

JCG/1-29-70

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Camels* TITLE Authorized Agent DATE 6-2-71

APPROVED BY *[Signature]* TITLE SUPERVISOR DISTRICT 1 DATE JUN 4 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 3 1971

OIL CONSERVATION COMM.
HOBBS, N. M.