

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
------------------------------

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Union Oil Company of California</b>	8. Farm or Lease Name <b>Hume Queen Unit</b>
3. Address of Operator <b>c/o Hobbs Pipe &amp; Supply Company, Box 2010, Hobbs, N. M.</b>	9. Well No. <b>5</b>
4. Location of Well UNIT LETTER <b>J</b> , <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>8</b> , TOWNSHIP <b>16-S</b> RANGE <b>34-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Hume Queen</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4146' KB</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 25 sx cement plug from 3932'-3948'.
2. Spotted a 25 sx cement plug at 5-1/2 casing stub at 510'.
3. Spotted a 25 sx cement plug at 8-5/8 casing shoe at 300'.
4. Spotted a 10 sx cement plug at surface with marker.
5. Hole was loaded with mud-laden fluids.
6. Well was plugged and abandoned on 2/4/71.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *John W. Ryan* TITLE Agent DATE 2/8/71

APPROVED BY *John W. Ryan* TITLE Geologist DATE

CONDITIONS OF APPROVAL, IF ANY: