

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Free   
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name None
2. Name of Operator ROGER C. HANKS	8. Name of Lease Owner Graham
3. Address of Operator 606 Wall Towers West, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>North</u> LINE, SECTION <u>29</u> TOWNSHIP <u>16S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Unit Undesignated-Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3923.1	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-13-69 Operator plans to plug and abandon the well by the following method:  
 Plug #1 set at 12980 - 13040' with 25 sacks cement  
 Plug #2 set at 11590 - 11650' with 25 sacks cement  
 Plug #3 set at 9540 - 9600' with 25 sacks cement  
 Plug #4 set at 8190 - 8250' with 25 sacks cement  
 Plug #5 set at 6140 - 6200' with 25 sacks cement  
 Plug #6 set at 4185 - 4245' with 25 sacks cement  
 Surface plug set with 10 sacks cement with marker indicating well name, location, etc.

Location will be cleared according to New Mexico OCC rules and regulations and commission will be notified when same is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Roger C. Hanks by Wanda Sanders TITLE Operator DATE 11-14-69

APPROVED BY John W. Runyan TITLE Geologist DATE NOV 20 1969

CONDITIONS OF APPROVAL, IF ANY:

