

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
V-488

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Great Western Drilling Company	8. Farm or Lease Name State 82
3. Address of Operator P.O. Box 1659, Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> <u>1,980</u> FEET FROM THE <u>North</u> LINE AND <u>1,980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>18</u> TOWNSHIP <u>15-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat Morton Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 4,050.1' KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well Data:

T.D. 10,700', PBSD 10,651', elev. 4,031.1' GR & 4,050.1' KB.
13-3/8" OD, 48#/ft. csg set @ 445.99' KBM in 17 1/2" hole w/425 sxs, 12 yds Redi-mix + 1-3/8 yds pea gravel, top surface.
9-5/8" OD, 36 & 40#/ft. csg set @ 4,675.66' KBM in 12 1/4" hole w/650 sxs, top cmt 3,160'.
5 1/2" OD, 17 & 20#/ft. csg set @ 10,681' KBM in 7-7/8" hole w/1,620 sxs + 140,000 SCF nitrogen, T-cmt. 5,220'.
Squeezed perfs: 10,200'-10,215' (15 holes).
Completed perfs: 10,200'-10,204' (5 holes) Bough C, 10,421.5'-10,439.5' (19 holes) & 10,466'-10,478' (12 holes) Bough D.

Note: Junk in hole, top of fish or junk at 6,631'. Items left in hole consist of 3,856' of 2-3/8" OD, tbg which includes mud anc., P.N., S.N., tbg anc., 2"x1 1/4"x20' pump, 9-7/8" steel rods & 47 1" fg rods which are between the 2-3/8" tbg & 5 1/2" csg (47 1" fg rods 1,762.5') probably on top of tbg anc.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF DRILLING OPERATIONS FOR THE C-103

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. B. Meyer TITLE Ass't. to Gen. Supt. DATE 5-15-87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAY 18 1987

CONDITIONS OF APPROVAL, IF ANY:

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
V-488	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Great Western Drilling Company	8. Farm or Lease Name State 82
3. Address of Operator P.O. Box 1659, Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> , <u>1,980</u> FEET FROM THE <u>North</u> LINE AND <u>1,980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>18</u> TOWNSHIP <u>15-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat Morton Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 4,050.1' KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Formation Tops:

T - Anhy	1,837'	T - Wolfcamp	9,630'
T - Yates	2,938'	T - Penn	10,228'
T - Queen	3,812'	T - Bough C	10,460'
T - San Andres	4,610'	T - Bough D	10,483'
T - Glorieta	6,231'		
T - Abo	7,360'		

Proposed Plugging Procedure:

1. Set cmt retainer above fish @ 6631'. Est. ret. @ 6,500' & squeeze w/300 sxs & displace - leave 5 sxs cmt on top of retainer.
2. Pull tbg to 6,359' and load hole w/salt gel mud consisting of 10# brine w/25# of gel per barrel. (150 bbls.) & (3,750# gel, 75 sxs).
3. After shooting & pulling 5½" csg, est. 5½" csg stub @ 5,100'. Set 50' plug in stub & 50' plug in 7-7/8" hole (6 sxs in & 19 sxs out) total 25 sxs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M.A. Hylton TITLE Ass't. to Gen. Supt. DATE 5-15-87

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SECRET (S)

MAY 15 1987

DCE

Records Office

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
V-488

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Great Western Drilling Company	8. Farm or Lease Name State 82
3. Address of Operator P.O. Box 1659, Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> <u>1,980</u> FEET FROM THE <u>North</u> LINE AND <u>1,980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>18</u> TOWNSHIP <u>15-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat Morton Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 4,050.1' KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 9-5/8" csg shoe @ 4,676'. Set 100' plug (50' below, 17 sxs & 50' above, 20 sxs) total 37 sxs.
- After shooting & pulling 9-5/8" csg, est. 9-5/8" csg stub @ 3,000'. Set 100' plug (50' in, 21 sxs & 50' out in 12 1/4" hole, 39 sxs) total 60 sxs.
- 13-3/8" csg shoe @ 446'. Set 100' plug (50' below, 39 sxs & 50 in, 42 sxs) total 81 sxs.
- Set 10 sx surface plug (0'-12') & dry hole marker.

THIS DOCUMENT IS THE PROPERTY OF THE NEW MEXICO OIL CONSERVATION COMMISSION. IT IS LOANED TO YOU FOR YOUR INFORMATION AND USE ONLY. IT IS NOT TO BE REPRODUCED OR DISTRIBUTED TO OTHERS WITHOUT THE WRITTEN PERMISSION OF THE COMMISSION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M.B. Myer TITLE Ass't. to Gen. Supt. DATE 5-15-87

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: