

DISTRICT I
P.O. Box 1980, Hobbs, NM 88241-1980

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, New Mexico 87505

DISTRICT II
811 S. First Street, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-28415 28781
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-6667
7. Lease Name or Unit Agreement Name NORTHEAST KEMNITZ
8. Well No. 9
9. Pool Name or Wildcat KEMNITZ MORROW
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4105' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator ELK OIL COMPANY	
3. Address of Operator POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-0310	
4. Well Location Unit Letter G : 1980 Feet From The NORTH Line and 1980 Feet From The EAST Line Section 16 Township 16 SOUTH Range 34 EAST NMPM LEA County	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)
SEE RULE 1103

INTEND TO PLUG AND ABANDON WELL AS FOLLOWS:

SET 35 SXS PLUG INSIDE 5 1/2" CASING @ 13,000' AND TAG.
SET 100' PLUG INSIDE 5 1/2" CASING @ 10,000'.
SET 100' PLUG INSIDE 5 1/2" CASING @ 7,000'.
RECOVER 5,500' OF 5 1/2" CASING.
SET 100' PLUG (50 IN / 50 OUT) @ 5,550'.
SET 100' PLUG (50 IN / 50 OUT) @ 4,482'. (8 5/8 SHOE)
SET 100' PLUG @ 2,000'. (TOP OF SALT).
SET 10 SXS SURFACE PLUG.
INSTALL DRY HOLE MARKER.
CIRCULATE HOLE WITH 10# MUD.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE		TITLE	PRESIDENT	DATE	9/21/98
TYPE OR PRINT NAME	JOSEPH J. KELLY	TELEPHONE NO.	505-623-3190		

(This space for State Use)

APPROVED BY	ORIGINAL SIGNED BY CHRIS WILLIAMS	TITLE		DATE	OCT 06 1998
CONDITIONS OF APPROVAL, IF ANY	DISTRICT I SUPERVISOR				

JK

✓
dm